

9-19-89  
7090



UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

0010

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 89-28-8-2

To the following Permittee or Operator:

Name U.S. Fuel Company

Mine Hiawatha Complex  Surface  Underground  Other

County Carbon State Utah Telephone 343-2471

Mailing Address Hiawatha, Utah 84527

State Permit No. ACT/007/011

Ownership Category  State  Federal  Fee  Mixed

Date of inspection September 14-15, 19 89

Time of inspection 9:00 am to 6:15 PM  
8:15 am  a.m.  p.m. to 12:30 PM  a.m.  p.m.

Operator Name (other than Permittee) \_\_\_\_\_

Mailing Address \_\_\_\_\_

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  is not  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Sept 15, 1989 Time of service/ mailing 1:00  a.m.  p.m.

Jean Semborski Permittee/Operator representative Environmental Coordinator Title

Jean Semborski Signature

Daron R. Haddock Division of Oil, Gas & Mining representative Reclamation Specialist Title

Daron R. Haddock Signature #28 Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

2818



NOTICE OF VIOLATION NO. N 89-28-8-2

Violation No. 1 of 2

Nature of violation

Failure to maintain diversions through  
disturbed areas so as not to cause  
additional erosion

Provisions of act, regulations or permit violated

UMC 817.45 (e)

Portion of operation to which notice applies

diversion through upper rail yard (upper end)  
diversions at middle fork load out  
diversion at King #6 mine from upper to Middle pad  
Inlet diversion to South fork load out pond.  
Inlet diversion to pond 5 south

Remedial action required (including any interim steps)

Clean ditches where necessary  
provide erosion protection in areas where  
run off is going uncontrolled,  
maintain or re define ditches.

Clean coal material from middle fork ditch and  
from along the length of the ditch.

Abatement time (including interim steps)

Oct 16, 1989 4:00PM



NOTICE OF VIOLATION NO. N 89-28-8-2

Violation No. 2 of 2

Nature of violation

Failure to maintain a support facility in a manner which 1) prevents additional contributions of suspended solids to run off on stream flow outside the permit area and 2) minimizes erosion to the extent possible

Provisions of act, regulations or permit violated

UMC 817.181  
UMC 817.45 (i) and (iii)

Portion of operation to which notice applies

Mohr land pipeline. Break in pipeline approximately 0.3 miles above end of rail line.

Remedial action required (including any interim steps)

Repair leak in pipe line and any attendant erosional damage caused by the leak.

Abatement time (including interim steps)

- 1) September 18, 1989 at 4:00 PM, to repair leak in pipeline
- 2) October 2, 1989 to repair erosion.