

0018



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

RECEIVED

DR71  
*[Signature]*

MAY 28 1991

DIVISION OF  
OIL GAS & MINING

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

PERMIT NO.: ACT/007/011 Inspection Date: May 14-15, 1991  
 Permittee and/or Operators Name: U.S. Fuel Company  
 Business Address: P.O. Box A  
 City: Hiawatha State: Utah Zip: 84527  
 Mine Name: Hiawatha Complex County: Carbon State: Utah  
 Type of Mining Activity: Underground XX Surface Other  
 Company Official (s): Bob Eccli  
 State Officials (s): Stephen J. Demczak DOGM  
 Time of Inspection: 9:00 (X) a.m. ( ) p.m. to 2:00 ( ) a.m. (X) p.m.  
 Partial Complete: XX Date of Last Inspection: 4/16/91  
 Weather Conditions: Warm 60's  
 Acreage: Permitted 20,700 Disturbed 290 Regraded Seeded  
 Bonded 290 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( X )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( X )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( X )	( )	( )	( )
7. COAL PROCESSING WASTE	( X )	( )	( )	( X )
8. NONCOAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( X )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( )
13. REVEGETATION	( X )	( )	( )	( )
14. SUBSIDENCE CONTROL	( X )	( )	( )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( X )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( X )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )

INSPECTION REPORT COMMENTS

(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/011 INSPECTION DATE May 14,15, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

- (a) Sediment pond inspection was taken March 27, 1991 with no problems noted.
- (b) Slurry Ponds were inspected May 10, 1991 with no problems noted.
- (c) Refuge Piles #1 and #2 were inspected March 27, 1991.
- (d) NPDES - samples were taken on May 9, 1991 on discharge point Doo1 and Doo2. The results have not been acquired from the lab yet.
- (e) Insurance - No problems were noted.
- (f) AVS Field check taken.

4. HYDROLOGIC BALANCE:

b. Diversions:

The diversion ditches around the topsoil piles at Southfork and Northfork requires maintenance.

8. NONCOAL WASTE:

The Middlefork mine area is clean from non-coal waste material since the mine shut down.

16. ROADS:

Moreland pipeline was performing as designed with no water leaks.

Copy of report:

Mailed to: Bob Eccli (USFC)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39 Date: 5/24/91

