

0018



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*Jed*  
*QQA*

Norman H. Bangerter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

Permit No. ACT/007/011 Inspection Date: 30 July 1992  
Permittee and/or Operators Name: U.S. Fuel  
Business Address: P.O. Box A City: Hiawatha State: UT Zip: 84527  
Mine Name: Hiawatha Complex County: Carbon State: UT  
Type of Mining Activity: Underground  Surface  Other   
Company Officials: Bob Eccli State Officials: Stephen J. Demczak  
Time of Inspection: 9:00 a.m. - 12:00 p.m. Partial  Complete:   
Acreage: Permitted 20700 Disturbed 290 Regraded 0  
Seeded 0 Bonded 290 Date Last Inspected: 23 June 1992  
Weather Conditions: 90's warm Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( X )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )
19. AVS Check	( )	( )	( )	( )

Permit No. ACT/007/011 Inspection Date 30 July 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

U. S. Fuel has installed additional stream buffer zone markers at empheral stream located Middle Fork Canyon.

4. Diversions -

The diversions on the property appear to be functioning as designed and no violations of performance standard were issued. The diversion ditch located on the right hand side of the road going up Middle Fork did not show signs of erosion. The operator did comment to perform maintenance o this ditch by adding rip rap and gaben type structure.


4c. Sediment Pond and Impoundments -

The field inspection showed that all ponds contained small amounts of water, but none of the ponds were discharging at the time of the inspection. The ponds' inlet, outlet and slopes showed no signs of erosion.

11. Contemporaneous Reclamation -

The contractor for the removal of the preparation plant was to set up today. The plant will take close to a month to demolish. The bond amount for the plant is approximately three quarters of a million dollars. Possibly one of the slurry ponds will be reclaimed this year.

Copy of report:

Mailed to: U.S. Fuel Co.Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: 5 August 1992Inspector's Signature and Number:   
Stephen J. Demczak

#39