



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

DR74
ga

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/007/011 Inspection Date: January 29, 1992
Permittee and/or Operators Name: U.S. Fuel
Business Address: P.O. Box A City: Hiawatha State: UT Zip: 84527
Mine Name: Hiawatha Complex County: Carbon State: UT
Type of Mining Activity: Underground XX Surface Other
Company Officials: Bob Eccli State Officials: Stephen J. Demczak
Time of Inspection: 9:30 a.m. - 11:30 a.m. Partial X Complete:
Acreage: Permitted 20700 Disturbed 290 Regraded 0
Seeded 0 Bonded 290 Date Last Inspected: December 18, 1991
Weather Conditions: Teens, 8" snow Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>NOTES</u>
1. <u>PERMITS</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>(X)</u>
2. <u>SIGNS AND MARKERS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
3. <u>TOPSOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
b. <u>DIVERSIONS</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>(X)</u>
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>(X)</u>
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
f. <u>EFFLUENT LIMITATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
5. <u>EXPLOSIVES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
7. <u>COAL PROCESSING WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
8. <u>NONCOAL WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
10. <u>SLIDES AND OTHER DAMAGE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
11. <u>CONTEMPORANEOUS RECLAMATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
12. <u>BACKFILLING AND GRADING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
13. <u>REVEGETATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
14. <u>SUBSIDENCE CONTROL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
15. <u>CESSATION OF OPERATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
b. <u>DRAINAGE CONTROLS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
c. <u>SURFACING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
d. <u>MAINTENANCE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
17. <u>OTHER TRANSPORTATION FACILITIES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
19. <u>AVS Check</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>

Permit No. ACT/007/011 Inspection Date January 29, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits -

- a. The subsidence map was just received by U.S. Fuel from their contractor for review. The map and other information will be submitted in the annual report to the Division.
- b. The Division notified U.S. Fuel to change the acord form in the insurance to eliminate the word "endeavor" and to notify the Division of the change.

4b. Diversions -

The diversion ditches during the time of inspection were frozen and contained snow. There were no signs of flowing water.

4c. Sediment Ponds and Impoundments -

At the time of inspection, no ponds were discharging. Ponds contained small amounts of water which were frozen over. No apparent signs of erosion to inlet or outlet of pond S.

Copy of report:

Mailed to: U.S. Fuel Co.Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: February 3, 1992Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak