

UNITED STATES FUEL COMPANY

0006

P.O. BOX 887
PRICE, UTAH 84501



(801) 637-2252
FAX (801) ~~343-2344~~
637-1070

November 7, 1994

Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

**RE: Permit Change Application -- Catch Basin Designs NOV
Abatement Deficiencies Corrections; U.S. Fuel Company, Hiawatha
Mine, Permit ACT/007/011.**

94 2
Copy [Signature]
Dear Sirs,

U.S. Fuel Company is submitting the attached Appendix VII - 15 which contains additional designs for sediment capacity of the catch basins. The changes should correct the deficiencies noted in your letter of October 28.

Please give me a phone call if you have any questions.

Sincerely,

Gary E. Gray,
Mine Engineer

