

0017



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John
WAZ

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 30, 1990
9:15am - 1:20pm

Permittee and/or Operators Name: Genwal Coal Company
Business Address: Box 766, Wellington Utah, 84542
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012
Type of Mining Activity: Underground Surface Other Prep. Plant
County: Carbon
Company Official (s): Candy Manzanares
State Official(s): Lynn Kunzler
Partial: X Complete: Date of Last Inspection: October 29, 1990
Weather Conditions: Cool and cloudy.
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469
Enforcement Action: N90-17-8-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	(X)	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION 11/30/90

(Comments are Numbered to Correspond with Topics Listed Above)


4c. Sediment Ponds and Impoundments. All ponds and empoundments were checked for stability and appeared to be well maintained, with the exception of the slurry pipeline pond. The inlet on this pond had eroded to a gully 4-feet deep at the head cut. As a result, Nov. N90-17-8-1 was issued for failure to maintain sediment ponds. Abatement required the repair of the inlet structure by December 14, 1990.

11. Revegetation. The operator had recently requested an extension to implement the surface facility testplots as required by the permit transfer conditions until December 20, 1990. The Division approved this extension prior to this inspection. The operator was reminded of the necesecity of implementing the plots this fall.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Candy Manzanares - GCC,

Given to: Joe Helfrich & Daron Haddock, DOGM.

Inspectors Signature and Number:  #17 Date: 1/3/91