



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

10Q74

Jch

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 3/15/91
09:30 am-11:30 am

Permittee and/or Operator's Name: Genwal Coal Company
Business Address: Box 766, Wellington, UT, 84542
Mine Name: Wellington Prep. Plant Permit Number: Act 007/012
Type of Mining Activity: Underground Surface Other_x
County: Carbon Company Official(s): Candy Manzanares
State Officials(s): Sharon Falvey,
Federal Official(s): none
Partial: x Complete Date of last Inspection: 02/18/91
Weather Conditions: Damp from recent snow showers, cloudy
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5
Bonded 469 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	(x)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(x)	()	()	(x)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	()	()	(x)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(x)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	(x)	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 2/8/91

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

I supplied the permittee with a copy of the bonding and insurance information that is currently in the Division files. This copy includes the certificate of liability insurance.

4. Hydrology

b. Diversions

The operator has recently completed maintenance work on the North-North East edge of the slurry ponds. The area of maintenance lies on a bank between the western most part of a top soil storage area and the undisturbed drainage ditch. The permittee has built up the edge of the bank with soil, where a low point was beginning to form, to prevent disturbed area drainage from entering the ditch.

c. Sediment Ponds and Impoundments

The Heat Dryer Pond shows need of maintenance at the culvert inlet. No violation is issued because the original pond/culvert design size includes the water volume for coal washing operations which is not active at this time. Therefore, the original sizing was over-designed for the present use. Additionally, the culvert is able to transmit flow without diminution of the volume of transport. The operator has committed to maintain the culvert.

Copy of this Report:

Mailed to: Brian Smith (OSM), Candy Manzanares GCC

Given to: Joe Helfrich and Daron Haddock DOGM

Inspector's Signature & Number: Shawn K. Felvey #38 Date: 2/25/91