



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

QA 2077
#5

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/007/012 Inspection Date: April 28, 1992
Permittee and/or Operators Name: Genwal Coal Co.
Business Address: P.O. Box 766 City: Wellington State: UT Zip: 84542
Mine Name: Wellington Prep Plant County: Carbon State: Utah
Type of Mining Activity: Underground Surface Other XX
Company Officials: Jon Passic State Officials: Stephen J. Demczak
Time of Inspection: 12:30 a.m. - 2:30 p.m. Partial X Complete:
Acreage: Permitted 1,720 Disturbed 356 Regraded 1.5
Seeded 1.5 Bonded 469 Date of Last Inspection: March 11, 1992
Weather Conditions: 70's Warm Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>NOTES</u>
1. <u>PERMITS</u>	()	()	()	()
2. <u>SIGNS AND MARKERS</u>	(X)	()	()	(X)
3. <u>TOPSOIL</u>	()	()	()	()
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	()	()	()	()
b. <u>DIVERSIONS</u>	()	()	()	()
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	(X)	()	()	(X)
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	(X)	()	()	(X)
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	()	()	()	()
f. <u>EFFLUENT LIMITATIONS</u>	()	()	()	()
5. <u>EXPLOSIVES</u>	()	()	()	()
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	()	()	()	()
7. <u>COAL PROCESSING WASTE</u>	()	()	()	()
8. <u>NONCOAL WASTE</u>	()	()	()	()
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	()	()	()	()
10. <u>SLIDES AND OTHER DAMAGE</u>	()	()	()	()
11. <u>CONTEMPORANEOUS RECLAMATION</u>	()	()	()	()
12. <u>BACKFILLING AND GRADING</u>	()	()	()	()
13. <u>REVEGETATION</u>	()	()	()	()
14. <u>SUBSIDENCE CONTROL</u>	()	()	()	()
15. <u>CESSATION OF OPERATIONS</u>	()	()	()	()
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	()	()	()	()
b. <u>DRAINAGE CONTROLS</u>	()	()	()	()
c. <u>SURFACING</u>	()	()	()	()
d. <u>MAINTENANCE</u>	()	()	()	()
17. <u>OTHER TRANSPORTATION FACILITIES</u>	()	()	()	()
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	()	()	()	()
19. <u>AVS Check</u>	(X)	()	()	(X)

Permit No. ACT/007/012 Inspection Date April 28, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

Perimeter markers throughout the property should be reviewed to encompass the disturbed area. Also, repainting markers as needed throughout the permit is advisable.

4c. Sediment Ponds and Impoundments -

No sediment ponds were discharging during inspection. Ponds appear to be stable and no erosion is occurring.

4d. Other Sediment Control Measures -

The ASCA maps and sediment control measures should be reviewed with the field inspection. These appear to be several areas within the disturbed area which would qualify as an ASCA area.

19. AVS Check -

An AVS check was made with no new changes occurring.


Copy of report:

Mailed to: Genwal Coal Co.

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Date: May 5, 1992

Inspector's Signature and Number:  #39
Stephen J. Demczak