

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/013

DATE OF INSPECTION: 4/28/99

(Comments are Numbered to Correspond with Topics Listed Above)

Some recent rains had fallen on site, however no water was in the sediment ponds.

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Lila Canyon is a significant revision to the Horse Canyon Permit. The proposed Lila Canyon facilities area was visited and no recent disturbance was noted. Old disturbance (1-2 years ago) included: surveying stakes and two tracks from a backhoe presumable digging soil pits.

2. SIGNS AND MARKERS

Mr. Clark stated that he would put up the last two permit entry signs now that the road had dried.

4. HYDROLOGIC BALANCE:

Runoff was observed in the drainage from the facilities area to Sediment Pond #2, all runoff went to the pond. Vehicles had run over the berm. The berm now requires maintenance.

10. SLIDES AND OTHER DAMAGE:

A small fire (1/2 acre) had occurred, April 16, 1999, on site from perhaps a cigarette thrown from the vehicle. Only a small portion of the area was inside the disturbed area. The area is near the pump house. Sunnyside and E. Carbon Fire Depts. responded to the fire.

Only a small amount of vegetation was burned from the fire. The grass had begun to resprout already.

Copy of this Report:

Mailed to: OSM, Jay Marshall (U.A.E.), William W. Engels (IPA), Paul Clark

Given to: Joe Helfrich (DOGM)

Inspector's Signature

Amanda M. White #35 Date: 4/29/99