

0034



UtahAmerican Energy, Inc.

December 18, 2003

801-359-3940

Pam Grubaugh-Littig
 Permit Coordinator
 DOGM
 1594 West North Temple, Suite 1210
 Salt Lake, Utah 84114-5801

Subject: ACT/007/013 Horse Canyon Maintenance Work

Dear Ms Grubaugh Littig:

Pam as you are aware the Horse Canyon MRP is in the mid term review process. Some maintenance work needs to be done. After discussing the work with both Karl Housekeeper and Dave Darby a satisfactory plan has jointly been agreed upon. They suggested that I notify you of the work that will take place.

The channel slopes in the area of the scouring will be sloped at 1:1. Rock 18" or less will be used to armor the channel to prevent reoccurrence. The soil material removed from the regrading will be used to fill in the rock dust bin and the holes in the floor of the shop as per our approved plan. Any soil not used to fill the rock dust bin or holes in the floor of the shop, will be spread out on the area that was previously disturbed for the Phase II bond release work. All disturbance will be contained within the previously disturbed areas where the pond and culvert were removed for Phase II bond release, or on the un-reclaimed portal pad area where the rock dust bin is located. The re-disturbed areas will be seeded according to our currently approved seed mix.

Scamp Excavation out of Wellington will perform the maintenance work.

Should you have any questions or comments please give me a call.

Sincerely,

R. Jay Marshall

R. Jay Marshall P.E.
 Project Engineer

ducing
C/007/013
Copy Dave
Fax Karl

RECEIVED

DEC 18 2003

DIV OF OIL GAS & MINING