

0003

### Document Information Form

Mine Number: C/007/016

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: June 16, 1980

Explanation:

Inspection Memo

\_\_\_\_\_

\_\_\_\_\_

cc:

File in: C/007, 016, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

716

June 16, 1980

Inspection Memo  
To Coal File:

RE: Gordon Creek #2 Mine  
Beaver Creek Coal Co.  
ACT/007/016  
Carbon County, Utah

The above mentioned operation was given a complete inspection on June 3, 1980 by Joe Helfrich, Lee Spencer, and Mary Kay Stein from the Division and Lary Damrau and Dan Martinez from the Office of Surface Mining. They were accompanied by Dan Guy, Chief Engineer for the Beaver Creek Coal Company.

After completing a field tour of the surface facilities, the following violations were issued:

OFFICE OF SURFACE MINING

1. Public Law 95-87, Section 502 (a). Violation - Operating without a permit, the portion of the operation to which the notice applies: (a) road construction and culvert installations, North West of West portals. (b) Fan portal area.
2. 30 CFR 717.17(a), 30 CFR 211.40 (b). Violation - Failure to pass surface drainage from the disturbed area through sedimentation ponds. The portion of the operation to which the notice applies is the drainage from the surface facilities areas.
3. 30 CFR, Section 717.17(a), 30 CFR 211.40(b). Violation - Failure to meet effluent limitations. The portion of the operation to which the notice applies was from water samples taken 17 April, 1980 and 2 May 1980 from surface water monitoring point 2-2-w, South and West of the surface facilities area.

Note: This violation will be vacated immediately upon verification of modification of water sampling points. Reason: O.S.M. approved plan is inadequate establishing additional points will protect operator against not exceeding effluent limitations. Move lower point closer to permit area, and establish additional point above permit area.

4. 30 CFR, Section 717.17 (c)(3), 30 CFR 211.40(b). Violation - Failure to design, construct and maintain temporary or permanent diversion structures to prevent contributions of suspended solids to stream flow. The portion of the operation to which the notice applies is the diversion of natural drainage of Bryner Canyon.
5. 30 CFR, 717.17(j)(1), 30 CFR 211.40(b). Violation - Failure to maintain access and haulroads so as to prevent additional contributions of suspended solids to stream flow. The portion of the operation to which the notice applies is the access and haul roads within the permit area.

File in:  Confidential  
 Shelf  
 Expandable  
Refer to Record No. 0003 Date 6/16/80  
In CI 007, 016, Internal  
For additional information

STATE VIOLATIONS

1. MC 717.11(b). Violation - No authorization to operate was available for inspection. The notice applies to: (a) road construction and culvert installation, North West of west portals. (b) Fan portal area.
2. MC 717.17(a). Violation - Failure to pass surface drainage from the disturbed area through sedimentation ponds. The notice applies to the drainage from the surface facilities.
3. MC 717.17(a). Violation - Discharge from disturbed area does not meet applicable O.S.M., State and EPA regulations. The notice applies to water samples taken 17 April 1980, and 2 May 1980 from surface water monitoring point 2-2-w, South and West of the surface facilities area.

Note: See O.S.M. violations #3 above.

4. MC 717.17(c) Diversions are not designed, constructed or maintained as to prevent contributions of suspended solids to stream flow. The notice applies to the natural drainage of Bryner Canyon.
5. MC 717.17(j) Roads and associated facilities are not constructed or maintained as to prevent additional contribution of suspended solids to stream flow. The notice applies to access and haulroads within the permit area.

The following are remedial action required for each violation:

1. Submit proposed mining plans to this State regulatory authority and to OSM. Proposed plans must be complete and adequate or must be supplemented or modified as determined by the State Regulatory Authority or OSM. Plans must be implemented immediately upon approval.
2. Pass all drainage from affected areas through sedimentation structure.
3. None (see note violation #3).
4. Maintain diversion structure to prevent additional contributions of suspended solids to the natural stream flow.
5. Maintain access and haulroads to prevent additional contributions of suspended solids to the natural stream flow.

Inspection Memo  
To Coal  
ACT/007/016  
June 16, 1980  
Page Three

All violations have July 7, 1980 as a set abatement time with the exception of violation #3 which will be vacated upon verification.

*Mary Kay Stein*  
MARY KAY STEIN  
RECLAMATION OFFICER

MKS/lml

cc: Murray Smith, OSM

Statistics Vehicle #EX 68237 - 695 miles  
#EX 68804 - 300 miles

Mary Kay Stein	\$136.44
Lee Spencer	120.00
Joe Helfrich	120.00
Jim Smith	34.11
	<hr/>
	\$410.55