

0018

### Document Information Form

Mine Number: C/007/016

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: May 27, 1983

Explanation:

Inspection Memo

cc:

File in: C/007, 016, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

May 27, 1983

Inspection Memo  
to Coal File:

RE: Beaver Creek Coal Company  
Gordon Creek #2 Mine  
ACT/007/016  
Folder No. 7  
Carbon County, Utah

A partial inspection was conducted at the above noted minesite by John Whitehead on May 20, 1983 accompanied by John McNeal of Beaver Creek Coal Company. The purpose of the inspection was to follow up on several areas of concern which were noted during the previous inspection.

The area adjacent to the fan at the extreme western end of the minesite where snow removal activities had pushed material over the edge of the pad onto the downslope had been addressed and appeared to be in good stable condition. A berm at the top of the slope had not been constructed, thus leaving the potential for material over the side again.

The undisturbed diversion which runs along the southern end of the minesite appeared to be blocked partly by slough from the highwall near the bathhouse. This will need to be addressed as a maintenance item.

During the inspection it was observed that the sediment pond was discharging and a sample was taken. Additionally the belt which conveys the sediment pond discharge downslope into the Bryner Creek drainage was in a state of disrepair. This will need to be reestablished to assure that erosion doesn't occur from the discharge out of the sediment pond.

The Beaver Creek Coal Company operations temporarily ceased mining coal on May 2, 1983. Dan Guy of BCCC indicated that a letter addressing the temporary cessation requirements of UMC 817.131 would be forwarded to the Division in the very near future.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0018 Date 5-27-83  
In C/ 007, 016, Internal  
For additional information


INSPECTION MEMO TO COAL FILE

ACT/007/016

May 27, 1983

Page Two

A culvert had recently been installed at the top of the stairs which go from the coal loading area to the mine office area. This had been noted as an area of concern in the previous inspection and appeared to be well taken care of.



JOHN J. WHITEHEAD  
FIELD SPECIALIST

JJW/lm

cc: Tom Ehmett, OSM  
Dan Guy, BCCC  
Joe Helfrich, DOGM

Statistics:

Vehicle: EX #45424 - 441 miles  
Per Diem: 1 person X 1 day, 10 hours = \$50.78  
Grant: A & E