

0025

February 8, 1983

Memo to Coal File:

#7

RE: Gordon Creek #2 Mine
Beaver Creek Coal Company
ACT/007/016
Carbon County, Utah

A follow up inspection of the Gordon Creek #2 minesite was conducted on January 18, 1983 by Scott Raymond and Sandy Pruitt. At the time of this inspection all disturbed area snow had been retrieved from the seeded area northeast of the bathhouse and downstream from the sediment pond and stockpiled in the designated snow disposal site at the west end of the sediment pond. Disturbed area snow had also been retrieved from on top of the berm along the undisturbed drainage ditch to the south of the loadout. The inlet to the sediment pond had been reestablished, the ditch and culvert draining the loadout area into the sediment pond had also been cleared of obstruction. A water bar was established across the mine access road to divert mine yard drainage toward the sediment pond. NOV #1 of 1 (N82-2-13-1) was terminated effectively January 18, 1983.

SANDY PRUITT^{SP}
FIELD SPECIALIST

SP/lm

cc: Tom Ehmett, OSM
Joe Helfrich, DOGM
Scott Raymond, BCCC

Statistics:

Vehicle: #EX 45424 - 538 miles
Per Diem: 1 person x 1 day, 9 hrs. = \$50.78
Grant: A & E