

0001

December 27, 1984

TO: Coal File, Inspection and Enforcement File
FROM: Ken Wyatt, Mining Field Specialist *KW*
RE: Beaver Creek Coal Company, Gordon Creek #2 and #7
Mine, ACT/007/016, #7, Carbon County, Utah

A partial inspection of the above referenced mine was conducted on December 13, 1984 by Ken Wyatt and Tom Wright, Mining Field Specialists for the Division. Mr. Dan Guy representing Beaver Creek Coal Company accompanied these inspectors in the field. The weather was partly cloudy and cold with recent snow.

Due to the cold weather and recent snow, no runoff was occurring. Snow removal operations to date have not necessitated utilizing the #3 and #6 Mines for snow storage. Room still exists on the #2 and #7 Mine area for additional snow storage. Currently, snow is piled directly west of the sediment pond.

The sediment pond had been decanted since the previous inspection. The water level was below the level of discharge. The sediment level and need for pond cleaning was discussed with the operator. At this time, it does not appear in need of excavation, but should be examined next year following spring runoff.

No compliance problems were encountered.

btb

cc: Donna Griffin
Dan Guy
Mary Boucek
Joe Helfrich

Statistics:

See Gordon Creek #3 and #6 Mines memo dated ??????
0379R-25