

0011

September 28, 1984

TO: Memo to Coal File, Inspection and Enforcement
FROM: Barton Kale, Field Specialist *BOK*
RE: Beaver Creek Coal Company, Gordon Creek #2 Mine,
ACT/007/016, Folder #7, Carbon County, Utah

A partial inspection was conducted on August 28, 1984 by Barton Kale and Tom Wright of the Division. The inspectors were accompanied by Dan Guy of Beaver Creek Coal Company

The water fill up area was in good shape. This area has been maintained in a satisfactory fashion for quite some time. This area has been a constant problem in the past but it is evident that the operator is making an effort at this site.

The #7 Mine portals have been mined to the approved 140 feet.

The undisturbed diversion that goes around the sediment pond and topsoil pile has received additional work. At the request of the inspector the operator extended the channel lining, leaving an additional 75 feet to protect the diversion.

The topsoil stockpile to the south of the sediment pond is lacking a completed berm. The north side is the area in question. The operator committed to completing the work by the next inspection.

Power poles that were inspected have been modified to become raptor proof.

The gabions to be installed below the cross culverts have been installed with the exception of one.

The silt fence at the stock pond is in need of repairs. The fence shows signs of undercutting.

re

cc: Donna Griffin
Dan Guy
Mary Boucek
Joe Helfrich

Statistics: See Gordon Creek #3 & #6 mine memo dated September 28, 1984

00380-9