



0018

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Scott M. Matheson, Governor  
Temple A. Reynolds, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

November 9, 1984

Mr. Dan W. Guy, Manager  
Permitting and Compliance  
Beaver Creek Coal Company  
P. O. Box 1378  
Price, UT 84501

Dear Mr. <sup>Alan</sup> Guy:

RE: Updating Mining and Reclamation Plans, Beaver Creek Coal Company, Gordon Creek #2 Mine, ACT/007/016, #2, Carbon County, Utah

Recently it has come to the Division's attention that our File and Work copies for the above referenced mine are not current, as compared to those of the Office of Surface Mining (OSM). Shortly before the end of the permitting process, the OSM required Beaver Creek Coal Company (BCCC) to add a portion of the Class I road, from approximately the mine gate down to the turnoff up to the C & W Mine, into the permit area. This necessitated certain text and figure (map) changes to be made in June or July 1984. The Division copies of the mine plan cannot be updated until these revised pages and figures have been submitted to the Division. It should be noted that all appropriate maps which designate the permit area boundary must be changed to reflect the true boundary as it is permitted.

It is suggested that BCCC contact the Division to set up a convenient time when the MRP on file with the Division can be compared to the most current copy of the MRP utilized by BCCC. Please contact Steve Cox or Mary Boucek at your earliest convenience.

Sincerely,

Mary M. Boucek  
Permit Supervisor/  
Reclamation Biologist

btb  
cc: Ron Daniels  
Steve Cox  
88130-92