

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Governor
Executive Director
Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

June 18, 1984

Mr. Dee C. Hansen
State Engineer
Division of Water Rights
1636 West North Temple
Salt Lake City, Utah 84116


RE: Additional Information
Submittal
Beaver Creek Coal Company
Gordon Creek #2 Mine
ACT/007/016, Folder #2
Carbon County, Utah

Dear Mr. Hansen:

Enclosed please find one copy of additional information submitted by Beaver Creek Coal Company (BCCC) for the Gordon Creek #2 Mining and Reclamation Plan (MRP). This submittal is in addition to the Company's June 6, 1984 submittal, both relating to problems that were encountered by the Company at the site of the Southwest Lease (Gordon Creek #7) surface development area as a result of unexpected runoff generated during highwall construction. Your expeditious review of this material and comments, if necessary, will be most appreciated by both the Division and BCCC.

Should you have any questions, please contact Mary Boucek of the Division as soon as possible.

Sincerely,



James W. Smith, Jr.
Administrator
Mineral Resource Development
and Reclamation Program

JWS/mmb:jvb
cc: M. Boucek, DOGM
S. Cox, DOGM
88130-17

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Scott M. Mainwaring, Governor
Deputy Secretary, Division Director
James W. Smith, Jr., Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

June 18, 1984

Mr. Kenneth Alkema
Department of Health
Division of Environmental Health
P. O. Box 2500
Salt Lake City, Utah 84101


RE: Additional Information
Submittal
Beaver Creek Coal Company
Gordon Creek #2 Mine
ACT/007/016, Folder #2
Carbon County, Utah

Dear Mr. Alkema:

Enclosed please find one copy of additional information submitted by Beaver Creek Coal Company (BCCC) for the Gordon Creek #2 Mining and Reclamation Plan (MRP). Problems were encountered by the Company at the site of the Southwest Lease (Gordon Creek #7) surface development area as a result of unexpected runoff generated during highwall construction, thus necessitating changes to the MRP which is currently in the final stages of the review process. Your expeditious review of this material and comments, if necessary, will be most appreciated by both the Division and BCCC.

Should you have any questions, please contact Mary Boucek of the Division as soon as possible.

Sincerely,



James W. Smith, Jr.
Administrator
Mineral Resource Development
and Reclamation Program

JWS/btb

cc: M. Boucek, DOGM

S. Cox, DOGM

88130-12