

0001



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

*Rec'd 1-15-87
Ent. 1-15-87*

John
Norman H. Baugher, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 12/22/86 10:00AM

Permittee and/or Operators Name: Beaver Creek Coal Company
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: Gordon Creek #2&7 Permit Number: ACT/007/016
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Dan Guy
State Official(s): Phil Ralphs&Tom Munson
Partial: Complete: Date of Last Inspection: 11/19/86
Weather Conditions: Partly Cloudy
Acreage: Permitted 2289 Disturbed 9 Regraded Seeded Bonded 9
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/016

DATE OF INSPECTION 12/22/86

(Comments are Numbered to Correspond with Topics Listed Above)

4b.) DIVERSION'S:

All of the surface water diversions were inspected and found to be in good repair. They all appeared to be frozen and were not conveying water. In areas where seeps exist there appeared to be some build up of ice in the diversions but did not pose any immediate problem at this inspection.

4c.) SEDIMENT PONDS AND IMPOUNDMENTS:

The sediment pond was inspected and was not discharging due to the lack of runoff.

4d.) OTHER SEDIMENT CONTROL MEASURES:

All of the straw bales and silt fences were inspected and were too frozen or snowed in to determine their effectiveness for spring runoff. Come spring time, it is recommended, that the operator examine all these structures to see if they need to be replaced or repaired to insure their effective treatment of sediment laden waters.

Copy of this Report:

Mailed to: CC. Donna Griffin (OSM) & Dan Guy (BCCC)

Given to: Joe Helfrich, John Whitehead, Tom Munson

Inspectors Signature and Number:

Thomas Munson

Date:

1/12/87