

0029

File A11007/016 #2

BEAVER CREEK Coal Company

Post Office Box 1378
Price, Utah 84501
Telephone 801 637-5050



April 20, 1988

RECEIVED

APR 22 1988

**DIV. OF OIL, GAS & MINING
PRICE, UTAH**

Mr. Lowell P. Braxton
Administrator
Utah Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attention: Mr. D. Wayne Hedberg

RE: Request to Amend
Subsidence Control Plan
Huntington Canyon No.4 Mine
INA/015/004-87A; #3
Emery County, Utah

Dear Mr. Braxton:

Enclosed are 14 copies of a revised page 3-48a for the Huntington Canyon No.4 Mine subsidence monitoring amendment. This amended page reflects the requirements of Mr. Hedberg's conditional approval letter of Dec. 8, 1987, and should replace the existing page 3-48a in the approved M.R.P.

I have also forwarded 2 copies of the latest mine maps to the U.S. Forest Service as requested. A copy of the transmittal letter and 1 set mine maps is also enclosed for your reference.

If you need any further information, please let me know.

Respectfully,

Dan W. Guy
Manager Permitting/Compliance

cc: Johnny Coffey
File

3.4.8.4 Subsidence Monitoring Plan (continued)

The subsidence monitoring program was suspended in 1987 after eight years of monitoring showed no effects from subsidence, and the U.S. Forest Service suspended the program.

Accordingly, Beaver Creek Coal Co. will suspend further subsidence monitoring at the Huntington Canyon No. 4 Mine. An annual surface inspection will continue to be conducted to identify material damage, and submitted to the Division with the annual report.

If the U.S.F.S. resolves its problems with the aerial monitoring, any available information on vertical movement from the 1980 - 1986 surveys will be submitted to the Division. If such data shows substantial subsidence, additional data will be acquired under the resumed program. If the program should be reinstated, Beaver Creek Coal Company will acquire at least one additional suite of aerial photography and attendant vertical movement data prior to bond release.

(Note: Delete pages 49 through 54 and Plate 3-7)