

5-23-2075



0006

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

RUS

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

WILL  
REVISED 4/18/89

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: March 2, 1989  
1:00 p.m. - 4:00 p.m.

Permittee and/or Operators Name: Beaver Creek Coal  
Business Address: P.O. Box 1378 Price, UT 84501  
Mine Name: Gordon Creek 2&7 Permit Number: ACT/007/016  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon State: Utah  
Company Official(s): Dan Guy  
State Official(s): Bill Malencik  
Partial:  Complete:  Date of Last Inspection: Feb. 1-2, 1989  
Weather Conditions: Heavy snow  
Acreage: Permitted 2289 Disturbed 9 Regraded      Seeded      Bonded 9  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( X )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( X )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/016

DATE OF INSPECTION March 2, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

This partial inspection was made in the field. The office records were not reviewed. Weather conditions at the mine site were adverse to making a detailed inspection. Twenty-two inches of snow was on the ground; six inches of new snow had fallen from about 11 am to 3 pm. ✓

2. SIGNS AND MARKERS:

Some signs and markers were observed that lie adjacent to the areas that had been cleaned of snow. Others because of weather conditions were not observed.

3. TOPSOIL:

The upper topsoil pile is covered with snow. The lower topsoil pile having a southerly exposure was also observed. This topsoil pile is snow covered, it was noted that the silt fence next to the highwall is preventing soil like material from encroaching on the topsoil pile.

16. ROADS:

The road from Sweets Canyon were snow plowed but slick. Truck hauling had been stopped about noon.

Copy of this Report:

Mailed to: Dan Guy, BCCC

Mailed to SLC for: Brian Smith OSM, Joe Helfrich DOGM

Filed to: PFO



Inspectors Signature and Number: Wm J. Malencik #26 Date: April 17, 1989