



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MININGNorman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

August 23, 1990

TO: Pamela Grubaugh-Littig, Permit Supervisor

FROM: Susan M. White, Reclamation Biologist *SMW*

RE: Sediment Ponds As-Built Maps, Beaver Creek Coal Company, Gordon Creek #2, #7 and #8 Mines, ACT/007/016, Folder #2, Carbon County, Utah

Synopsis and Analysis

On August 22, 1990 during a complete inspection of Gordon Creek 2, 7, and 8 mines, a permit deficiency was noted. The as-built maps of Sediment Ponds 2, 7 and 8 showed no inlet points. Sediment Pond 2 has four inlets and Sediment Pond 7 has two inlets. The as-built map of the Sweets Pond did not show the drop structure (inlet) adjacent to the water truck fill area.

Recommendation

The operator should correct the above mentioned maps and submit for insertion into the Permit Application Package.

SMW/djh
cc. B. Malencik, DOGM, PFO
T. Munson, DOGM
AT