

0009

Mountain Coal Company
Trail Mountain Mine
Post Office Box 1378
Price, Utah 84501
Telephone 801 637-5050 (Price Office)
801 637-5203 (Mine Office)
801 748-2140 (Mine Site)

*Route Henry #2178
then Jose Trueman
then file*



RECEIVED

AUG 28 1991

DIVISION OF
OIL GAS & MINING

August 26, 1991

Donald A. Hilden, Ph.D., Chief
Permits and Compliance Section
Bureau of Water Pollution Control
Utah Division of Environmental Health
288 North 1460 West
P.O. Box 16690
Salt Lake City, Utah 84116-0690

Attn: Mr. Steve McNiel

Re: UPDES Permit UTG040003 —
Gordon Creek No. 2 Mine — *ACT/007/011 #7*
UPDES Permit UTG040004 —
Trail Mountain Mine —
ACT/015/009 #7


Dear Mr. Hilden:

At the request of Mr. McNiel, I have enclosed a revised copy of the applicable, above referenced discharge reports, showing the TDS values in pounds per day. The June flow value for the Gordon Creek No. 2 was extremely low (10.4 gallons per day); however, it was based on actual measurement.

In reference to the letter of non-compliance on TSS values for the Trail Mountain Mine, I neglected to state the period of non-compliance. Based on the sampling, the period of non-compliance was 5/28/91 to 6/25/91. The July sample shows the discharge to be back in compliance. I have included a copy of the preliminary lab report for July for your reference. The August discharge report is not yet available.

I hope this information will clear up any deficiencies in our reports. If you have any questions, or need any further information, please let me know.

Sincerely,



Dan W. Guy
Mgr. Permitting/Compliance

DWG/pd

Enclosures

cc: Donna Franklin, E.P.A.
Lowell Braxton, UDOGM
File