



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*John* *Page*

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: April 3, 1991  
2:00pm to 3:00pm

Permittee and/or Operator's Name: Beaver Creek Coal Company (BCCC)  
Business Address: P.O. Box 1378, Price, Utah 84501  
Mine Name: Gordon Creek #2, 7 & 8 Permit Number: ACT/007/016  
Type of Mining Activity: Underground X Surface      Other       
County: Carbon Company Official(s): Dan Guy  
State Officials(s): Susan White and Hugh Klein  
Federal Official(s): None  
Partial: x Complete      Date of last Inspection: 3/7/91  
Weather Conditions: Clear and cool  
Acreage: Permitted 2289 Disturbed 17.2 Regraded      Seeded       
Bonded 17.2 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	(X)	( )	( )	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(x)
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	(X)	( )
8. NONCOAL WASTE	(X)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	(X)	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	(x)
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/016 DATE OF INSPECTION: April 3, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Weather condition were clear and cool. Most of the mine site was still covered in snow.

3) Topsoil

The silt fence above the #2 yard topsoil pile was noted as damaged in the last inspection report. Mr. Guy said that the fence was repaired however additional rock falls had occurred with the current freeze and thaw weather. He did state that the entire fence would be replaced with routine spring maintenance.

4a) Diversions

Those drainage and diversions which were visible above the snow were clean.

4c) Sediment Ponds

The upper pond was covered with snow. The middle pond contained water and was filling. Sweets pond was still ice and snow covered.

16b) Roads: Drainage controls

The road drainage on the north side, immediately beyond the entrance gate requires rock removal.

Copy of this Report:

Mailed to: Dan Guy, BCCC; John Kathmann, OSM

Given to: Joe Helfrich, DOGM / Hugh Klein

Inspector's Signature & Number: *James M. White* #35 Date: 4/4/91