

0013



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

John
PSL

INSPECTION REPORT

INSPECTION DATE & TIME: 29 July 1992
14:00 to 17:00

Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: Gordon Creek 3 & 6 Permit Number: ACT/007/017
Type of Mining Activity: Underground X Surface Other
County: Carbon Company Official(s): Dan Guy
State Officials(s): Jess Kelley
Federal Official(s): None
Partial: X Complete: Date of last Inspection: 23 June 1992
Weather Conditions: Sunny and hot
Acreage: Permitted-668 Disturbed-28 Regraded-8 Seeded-28 Bonded-28
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/017 DATE OF INSPECTION: 29 July 1992

(Comments are Numbered to Correspond with Topics Listed Above)

An AVS check was performed. The permittee is shown as Mountain Coal Company on all bonding, insurance, permit and other forms.

2. SIGNS & MARKERS

Site identification sign and boundary markers are in place and in good condition.

4. HYDROLOGIC BALANCE

(b) Diversions--Roadside ditches are clean and in good repair. The ditch and small water bar structure on top of the upper pad area are in good repair.

(c) Sediment Ponds and Impoundments--Both cells of the sediment pond were dry and the pond had not discharged. The pond is in good condition. Its banks are vegetated and show no sign of erosion damage.

13. REVEGETATION

The #3 Portal Area fill is stable and in good condition. With the recent precipitation, the vegetation on the fill has improved and spread and the fill shows no sign of erosion damage.

In general, vegetation on the site appears to be in good condition. There is a thick growth of sweet clover, grass, and some sage. The vegetative cover appears to be functioning well to prevent erosion.

Copy of this Report:

Mailed to: Dan Guy/Mountain Coal; Bernie freeman/OSM

Given to: Joe Helfrich (DOGM); Price Field Office/DOGM

Inspector's Signature: Jesse W. Kelley #34 Date: 7/30/92