

0006



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

#3

Michael O. Leavitt  
Governor  
Ted Stewart  
Executive Director  
James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

**DIVISION OF OIL GAS & MINING  
FIELD VISIT FORM**

**Date:** October 23, 1996

**Time:** 12:30 p.m. to 2:00 p.m.

**Mine:** ACT/007/016, Gordon Creek 2, 7, and 8

**DOG M Staff:** Susan White, Robert Davidson

**Other Attendees:** Dan Guy, Leeland Sasser (NRCS)

Some snow still remained on the north facing slopes. The contractor was in the process of filling a presumed subsidence hole approximately 50 feet west of the disturbed area between the 7 and 8 Mine. Seeding of the 7 and 8 Mines were complete. Seeding of 2 Mine on the slope south of the channel was complete. A portion of the conveyor area and fill storage area had been seeded. The contractor was working on filling the 2 Mine and the conveyor bench.

Topsoil had been moved down to the topsoil pile in the 2 Mine area. Mr. Guy was told that a berm should be around the pile and that the oil barrels and stream cleaner should be stored in appropriate areas and not adjacent to the topsoil.

Mr. Guy was asked if the final grade of the conveyor area adjacent to the old fill storage met the grade as specified in the plan. He stated that Dave Darby instructed him to only fill the base of the expose rock outcrop. The area appeared to me to not meet the requirements of the plan.

I told Mr. Guy that the equipment in the county turn around should be moved and that the staging area within the disturbed area should be treated for sediment control.

Signature: Susan M. White Date 10/24/96  
Susan M. White

