

April 4, 2003

TO: Internal File  
THRU: Daron R. Haddock, Permit Supervisor  
FROM: David Darby, Senior Reclamation Specialist  
RE: 2000, 4<sup>th</sup>, Quarter Water Monitoring, Canyon Fuel Co., Gordon Creek 2,7, & 8, ACT/007/016-WQ00-4

**1. Was data submitted for all of the MRP required sites?** YES [ ] NO [ X ]  
*Identify sites not monitored and reason why, if known:*

There was no data submitted for the Left Fork of Bryner, above the #2 Mine, 2-11-W.

**2. On what date does the MRP require a five-year resampling of baseline water data.**  
*See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.*

**Resampling due:** Permit expires 08/28/2004

**3. Were all required parameters reported for each site?** YES [X] NO [ ]  
*Comments, including identity of monitoring site:*

**4. Were irregularities found in the data?** YES [ ] NO [X]  
*Comments, including identity of monitoring site:*

The Right Fork of Bryner Canyon showed no flow for the measurement in July and 200 gpm for the 4<sup>th</sup> quarter. Other streams showed increased flows over last quarter also. Likely a late summer rainstorm.

**5. Were DMR forms submitted for all required sites?**

1<sup>st</sup> month, YES [X] NO [ ]  
2<sup>nd</sup> month, YES [X] NO [ ]  
3<sup>rd</sup> month, YES [X] NO [ ]

*Identify sites and months not monitored:*

**6. Were all required DMR parameters reported?** YES  NO   
*Comments, including identity of monitoring site:*  
There were no discharges during the quarter.

**7. Were irregularities found in the DMR data?** YES  NO   
*Comments, including identity of monitoring site:*

**8. Based on your review, what further actions, if any, do you recommend?**

Request information for Site 2-11-W.