

Print Form

Submit by Email

Reset Form

Task #4556

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Canyon Fuel Company, LLC	Mine Name	Gordon Creek 2,7, & 8 Mines
Permit Number	C/007/0016	Permit expiration Date	2014-08-09
Operator Name	Canyon Fuel Company, LLC	Phone Number	+1 (970) 261-1425
Mailing Address	225 North 5th Street, Suite 900	Email	chansen@bowieresources.com
City	Grand Junction		
State	Colorado	Zip Code	81501

DOG M File Location or Annual Report Location

Excess Spoil Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Refuse Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Attached as an electronic file and listed under "Reporting of other Technical Data"
Other:		

OPERATOR COMMENTS

REVIEWER COMMENTS Met Requirements Did Not meet Requirements

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

The electronic files attached to the email submittal to the Division of this annual report also contain a scanned copy of the annual pond inspection of the Gordon Creek 2, 7 & 8 Mines Jacob Pond. The inspection was performed by Rich White, P.E. of EarthFax Engineering, Inc. The electronic file is titled "EarthFax Gordon Creek Pond Inspection 2013".

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements



EarthFax

**EarthFax
Engineering, Inc.**
Engineers/Scientists
7324 So. Union Park Ave.
Suite 100
Midvale, Utah 84047
Telephone 801-561-1555
Fax 801-561-1861
www.earthfax.com

July 27, 2013

Ms. Vicky Miller
Canyon Fuel Company
SUFCO Mine
597 South SR 24
Salina, UT 84654

Subject: Inspection of Gordon Creek Sedimentation Pond

Dear Vicky:

On July 19, 2013 I conducted an inspection of the sedimentation pond at the Gordon Creek No. 2/7/8 Mine. The pond was empty at the time of my inspection, and no water was flowing into or out of the pond. I observed no signs of instability in the embankment or the spillway, nor did I observe any sign of recent outflow from the pond.

I have attached four photographs of the pond area that I took during the inspection. These show the general condition of the pond at the time of my inspection.

It is my opinion that you may continue to use the pond in its current state.

Please contact me if you have any questions.

Sincerely,

Richard B. White, P.E.
President

Attachment






Photo 1: View of pond area from spillway.



Photo 2: Top of spillway (viewed downstream).



Photo 3: Spillway inlet from pond.



Photo 4: View of pond from upstream end.