

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

March 12, 2015

TO: Internal File

THRU: Steve Christensen, Permit Supervisor 

FROM: Amanda Daniels, Hydrologist 

SUBJECT: 2014 Third Quarter Water Monitoring, Mountain Coal Company, Gordon Creek 2, 7, & 8 Mine, C/007/0016, WQ14-3, Task ID #4668

The Gordon Creek 2, 7, & 8 Mine has been reclaimed and received Phase II bond release on all but 1.63 acres on March 7, 2007. The 1.63 acres contained a three-cell sediment pond which was reclaimed in October 2007. Water monitoring requirements for the period after Phase II bond release until final bond release are described in the MRP on page 7-56 and in Tables 7-17 and 7-18.

This report was prepared from monitoring data queried from the UDOGM database. The data that support this report were collected and submitted to the database by the Permittee. The data was downloaded into file O:\007016.GC2\Water Quality\Data\GordonCreek278WQ.xlsx for this review.

1. Was data submitted for all of the MRP required sites? YES NO

The Permittee is not required to monitor any springs or wells at the Gordon Creek 2, 7, & 8 Mine. Monitoring for UPDES discharges is no longer required as the sediment ponds and mine portals have been reclaimed.

Streams

The Permittee is required to monitor one intermittent stream (2-2-W), and three ephemeral stream sites (2-7-W, 2-8-W, 2-9-W) quarterly for flow, field measurements and laboratory parameters as outlined on Table 7-18 of the MRP.

All stream sites reported no flow except 2-2-W, which had a flow of 98 gpm.

2. Were all required parameters reported for each site? YES NO

3. Were any irregularities found in the data? YES NO

2-2-W, September – Temperature

4. On what date does the MRP require a five-year re-sampling of baseline water data.

The MRP does not require a five-year re-sampling of baseline water data.

5. Based on your review, what further actions, if any, do you recommend?

None