

Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Canyon Fuel Company, LLC	Mine Name	Gordon Creek 2, 7, & 8 Mines
Permit Number	C/007/0016	Permit expiration Date	August 27, 2019
Operator Name	Canyon Fuel Company, LLC	Phone Number	+1 (970) 261-1425
Mailing Address	225 North 5th Street Suite 900	Email	chansen@bowieresources.com
City	Grand Junction		
State	Colorado	Zip Code	81508

DOGM File Location or Annual Report Location

Excess Spoil Piles

- Required
 Not Required

Refuse Piles

- Required
 Not Required

Impoundments

- Required
 Not Required

Has met the minimum. Copies of inspections attached as an electronic file and listed under "Reporting of other Technical Data"

Other:

OPERATOR COMMENTS

REVIEWER COMMENTS

- Met Requirements Did Not meet Requirements

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

The electronic files attached to the email submittal to the Division of this annual report also contain a scanned copy of the annual pond inspection of the Gordon Creek 2, 7 & 8 Mines Jacob Pond. The inspection was performed by Rich White, P.E. of EarthFax Engineering, Inc. The electronic file is titled "Gordon Creek Annual Pond Inspection 2015".

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements

Jacob's Pond

Date: 3/23/2015
Time: 6:30

Inspector(s) Signature: *Judy A. Madala*

Quarterly Inspection Form

1st Quarter

	Yes	No	N/A	Action Required		Person Notified	Date Corrected	Comments/Remarks
				Yes/No	Yes/No			
Stability of Pond								
Pond stability/weakness	Stable			No				
Erosion/Stability of banks	Stable			No				
Vegetation problem around pond		X						
Hazardous Condition								
Any visible contaminants		X						
Hazardous condition observed		X						
Inlet Conditions								
Inlet functioning	X							
Culvert(s)/ditches functioning	X							
Principle & Emergency Spillways								
Water Discharging (rate)	No							
Pond water level	1/4 - 1/3 Full/ Ice Covered							
Spillway is clear of debris	Yes							
Oil skimmer			X					
Emergency spillway			X					
Primary spillway functioning	Yes							

Other Observations:

Jacob's Pond

Date 9/23/2015 Time 1600

Inspector(s) Signature *Lesley A. Madler*

Quarterly Inspection Form

	Yes			No			Action Required		Person Notified	Date Corrected	Comments/Remarks
	Yes	No	N/A	Yes/No	Yes/No						
Stability of Pond											
Pond stability/weakness	Stable			No							
Erosion/Stability of banks	Stable			No							
Vegetation problem around pond				No							
Hazardous Condition											
Any visible contaminants		X									
Hazardous condition observed		X									
Inlet Conditions											
Inlet functioning	X										
Culvert(s)/ditches functioning	X										
Principle & Emergency Spillways											
Water Discharging (rate)		X									
Pond water level		1/3 Full									
Spillway is clear of debris	Yes										
Oil skimmer			X								
Emergency spillway				X							
Primary spillway functioning	Yes										

Other Observations: Nothing was flowing at time of inspection. Area was being used by wildlife the vegetation showed signs of being heavily grazed.

EarthFax Engineering Group, LLC

7324 South Union Park Avenue, Suite 100, Midvale, Utah 84047 • 801.561.1555 • FAX 801.561.1861



EarthFax

June 3, 2015

Mr. Chris Hansen
Director of Environmental Compliance and
Government Relations
Bowie Resource Partners, LLC
225 N 5th Street, Suite 900
Grand Junction, CO 81501

Subject: Inspection of Gordon Creek Sedimentation Pond

Dear Chris:

On June 2, 2015 I conducted an inspection of the sedimentation pond at the Gordon Creek No. 2/7/8 Mine. The pond (also known as Jacob's Pond) was impounding water at the time of my inspection but was not discharging. I observed no signs of instability in the embankment or the spillway, nor did I observe any sign of recent outflow from the pond.

I have attached two photographs of the pond area that I took during the inspection. These show the general condition of the pond at the time of my inspection.

It is my opinion that you may continue to use the pond in its current state.

Please contact me if you have any questions.

Sincerely,

Richard B. White, P.E.
President

Attachment



BRP

JUN 08 2015

Received

Emailed C. Hansen 6/8/15



Photo 1 - View of pond from downstream embankment



Photo 2 - View of spillway with pond in background