



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

November 21, 1990

Mr. Dan Guy, Manager
Permitting & Compliance
Beaver Creek Coal Company
P.O. Box 1378
Price, Utah 84501

Dear Mr. Guy:

Re: Review of Highwall Designation, Beaver Creek Coal Company,
Gordon Creek #3 & #6 Mine, ACT/007/017, Folder #2, Carbon
County, Utah

Attached is a Technical Memorandum that reviews the above-referenced deficiency in the Gordon Creek #3 & #6 Mine reclamation plan.

Please provide three copies suitable for insertion into the approved Permit Application Package (PAP) by no later than December 20, 1990.

Sincerely,

A handwritten signature in cursive script that reads "Pamela Grubaugh-Littig".

Pamela Grubaugh-Littig
Permit Supervisor

jbe
Attachment
AT007017.1



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

November 14, 1990

TO: Pamela Grubaugh-Littig, Permit Supervisor
FROM: Susan M. White, Reclamation Soils Biologist *AMW*
RE: Highwall Designation, Hidden Valley, ACT/015/017, and
Gordon Creek #3 & #6, ACT/007/017, Folder #2

Synopsis and Analysis

During inspections at the above referenced mines, deficiencies were noted on the final reclamation maps. No highwalls were designated on the Hidden Valley maps, two exist above the coal seams. Highwalls were designated on the Gordon Creek #3 & #6 map, except one on the west side of the road.

Recommendation

The permittee must correct and replace the inaccurate maps.

jbe
cc: Jesse Kelley
AT015017.5