

September 19, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: David Lof, Mining Field Specialist *DL*
RE: Soldier Creek Coal Company, Soldier Canyon Mine,
ACT/007/018, Folder #7, Carbon County, Utah

On August 30, 1985 a partial inspection was conducted at the above mentioned mine site.

Sediment Pond, NOV N85-4-15-1

On September 3, 1985 the Division sent the operator a deficiency letter regarding plans submitted on July 1, 1985 for abatement of the NOV. The letter required that additional information on riprap design be submitted to the Division by September 20, 1985.

Sewage Lagoon Site

During my July 26, 1985 complete inspection, I asked the operator to maintain the ditch along the west side of the access road to the sewage lagoons prior to my next inspection. At the time of this inspection, I found that the operator had made a poor attempt at maintaining the ditch. I informed Dave Spillman of Soldier Creek that if the ditch did not meet design specifications in two weeks that a violation would be issued.

re

cc: Donna Griffin, OSM
Dave Spillman, Soldier Creek
Joe Helfrich, DOGM
Ken May, DOGM

Statistics:

Vehicle: EX 49611 - - 609 miles
Per Diem: 1 person X 2 days, 15 hours = \$123.14
Grant: A&E

0348Q-3