



0030 *RE 2-2-87*

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Jan SCL

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 23, 1987
9:30 a.m. - 10:30 a.m.

Permittee and/or Operators Name: Andalex Resources
Business Address: P. O. Box 902, Price Utah 84501
Mine Name: Centennial Project Permit Number: ACT/007/019
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Mike Glasson
State Official(s): Rick Summers, Holland Shepherd
Partial: Complete: Date of Last Inspection: 12-10-86
Weather Conditions: Overcast, cold, spotty snow
Acreage: Permitted 2360 Disturbed 31 Regraded 0 Seeded 0 Bonded 31
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION 2-18-87

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers:

As discussed in the previous inspection report (1-23-87), the operator committed to posting a permit boundary sign at the point where the operator's boundary crosses the haul road. This task still needs to be done. Identification signs are currently posted at the operator's gate, however, they are located approximately 100 yards south of the actual permit boundary.

Copy of this Report:

Mailed to: Michael Glasson, Donna Griffin
Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd Date: 2-23-86