



Rec DOGM, SLL  
by LAB  
5/23/88

LAB  
5-27-88

NO. N 88-28-3-1

notice of violation

To the following Permittee or Operator:

Name Andalex Resources

Mine Centennial Project  Surface  Underground  Other

County Carbon State Utah Telephone 801/637-5385

Mailing Address PO Box 902 Price, Utah 84501

State Permit No. ACT/007/019

Ownership Category  State  Federal  Fee  Mixed

Date of inspection May 19, 19 88

Time of inspection 8:30  a.m.  p.m. to 5:00  a.m.  p.m.

Operator Name (other than Permittee) Same

Mailing Address Same

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 5/19/88 Time of service/ mailing 5:30  a.m.  p.m.

Mike Glasson  
Permittee/Operator representative

Senior Geologist  
Title

Delivered at Mine site  
Signature

Daron R. Haddock  
Division of Oil, Gas & Mining representative

Reclamation Specialist  
Title

Daron R. Haddock  
Signature

#28  
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

2803



### NOTICE OF VIOLATION NO. N 88-28-3-1

Violation No. 1 of 1

Nature of violation

Failure to conduct coal mining activities  
in accordance with the terms and  
conditions of the permit and requirements  
of the regulatory program

Provisions of act, regulations or permit violated

UMC 771.19

Portion of operation to which notice applies

- 1. Surface & Ground water monitoring requirements, in particular field measurements. (No field measurements taken)
- 2. Sediment level markers are required by the MRP are are not in the sediment ponds.
- 3. Three ditches shown on Support Facilities map are not in the field as described a) west side of Apex Truck lead out (buried)

Remedial action required (including any interim steps)

- 1. Start taking field measurements of Surface & Ground water. b) west side of Shop area c) above lower pinnacle portals (not rip-rapped)
- 2. place required sedi level markers in ponds,
- 3. Fix ditches as shown in plan or provide alternate plans which are acceptable to DOGM.

Abatement time (including interim steps)

~~June 30th 5 PM~~  
June 20th 5 PM