



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

RECEIVED

MAY 28 1992

Handwritten initials/signature

Norman H. Bangertor
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

DIVISION OF OIL GAS & MINING

Permit No. ACT/007/019 Inspection Date: May 20, 1992
Permittee and/or Operators Name: Andalex Resources, Inc.
Business Address: P.O. Box 902 City: Price State: Utah Zip: 84501
Mine Name: Centennial Project County: Carbon State: Utah
Type of Mining Activity: Underground XX Surface Other
Company Officials: Mike Glasson State Officials: Stephen J. Demczak
Time of Inspection: 8:00 a.m. - 12:00 p.m. Partial X Complete:
Acreage: Permitted 3368 Disturbed 34 Regraded 0
Seeded 0 Bonded 34 Date of Last Inspection: April 21, 1992
Weather Conditions: Raining, 50's Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. <u>PERMITS</u>	()	()	()	()
2. <u>SIGNS AND MARKERS</u>	(X)	()	()	(X)
3. <u>TOPSOIL</u>	(X)	()	()	(X)
4. <u>HYDROLOGIC BALANCE:</u>				
<u>a. STREAM CHANNEL DIVERSIONS</u>	()	()	()	()
<u>b. DIVERSIONS</u>	(X)	()	()	(X)
<u>c. SEDIMENT PONDS AND IMPOUNDMENTS</u>	(X)	()	()	(X)
<u>d. OTHER SEDIMENT CONTROL MEASURES</u>	()	()	()	()
<u>e. SURFACE AND GROUNDWATER MONITORING</u>	()	()	()	()
<u>f. EFFLUENT LIMITATIONS</u>	()	()	()	()
5. <u>EXPLOSIVES</u>	()	()	()	()
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	()	()	()	()
7. <u>COAL PROCESSING WASTE</u>	()	()	()	()
8. <u>NONCOAL WASTE</u>	()	()	()	()
9. <u>PROTECTION OF FISH, WILDLIFE AND</u> <u>RELATED ENVIRONMENTAL VALUES</u>	()	()	()	()
10. <u>SLIDES AND OTHER DAMAGE</u>	()	()	()	()
11. <u>CONTEMPORANEOUS RECLAMATION</u>	()	()	()	()
12. <u>BACKFILLING AND GRADING</u>	()	()	()	()
13. <u>REVEGETATION</u>	()	()	()	()
14. <u>SUBSIDENCE CONTROL</u>	()	()	()	()
15. <u>CESSATION OF OPERATIONS</u>	()	()	()	()
16. <u>ROADS</u>				
<u>a. CONSTRUCTION</u>	()	()	()	()
<u>b. DRAINAGE CONTROLS</u>	()	()	()	()
<u>c. SURFACING</u>	()	()	()	()
<u>d. MAINTENANCE</u>	()	()	()	()
17. <u>OTHER TRANSPORTATION FACILITIES</u>	()	()	()	()
18. <u>SUPPORT FACILITIES</u> <u>UTILITY INSTALLATIONS</u>	()	()	()	()
19. <u>AVS Check</u>	()	()	()	()

Permit No. ACT/007/019 Inspection Date May 20, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

The sign at the north entrance to the property has been revised to have the correct address. The gate at the north end of the property leads to private property and roads.

3. Topsoil -

Several topsoil piles located at the mine site have adequate vegetation growing on them. Therefore, it was suggested that the permittee amend the plan to eliminate additional topsoil erosion measures such as berms and ditches. Those erosion measures presently serve no purpose.

4b. Diversions -

Disturbed and undisturbed diversions were inspected with the design standards. Several areas throughout the property will require maintenance shortly due to the above average rainfall experience this past week.

4c. Sediment Ponds and Impoundments -

The sediment ponds were inspected for erosion of inlets, outlets and slopes. Pond showed no signs of erosion or any other environmental problem.


Copy of report:

Mailed to: Andalex Resources, Inc.

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Date: May 22, 1992

Inspector's Signature and Number:  #39
Stephen J. Demczak