



007/019 #2

0008




ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860



September 17, 1993

State of Utah
Department of Natural Resources
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, Utah 84180-1203



Attn: Daron Haddock
Permit Supervisor

Re: ACT 007/019, Catch Basin B.

Dear Mr. ^{Man}Haddock:

On August 25, 1993, Andalex's Centennial Minesite received 0.73" of rain between 3:00 p.m. and 4:00 p.m. At this location, a ten-year storm event of one-hour duration is 0.68".

As a result of this storm, minor damage was sustained at the Catch Basin B location. Specifically, the dike between cells B3 and B2 was eroded to the extent that the only logical repair was to install a piece of culvert in the eroded channel. The dike will now function similarly to the one between cells B4 and B3, where a culvert was installed several years ago. Refer to the enclosed Plate 11 for additional details.

Please call with any questions.

Sincerely,

Michael W. Glasson
Senior Geologist

mwg/rr

Enclosure