

0014



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

ORZ
gh

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: XX Complete: Exploration

Inspection Date/Time: March 11, 1993/09:00am-11:00am

Date of Last Inspection: February 16, 1993

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019

Permittee and/or Operator's Name: Andalex Resources

Business Address: P. O. Box 902, Price, UT 84501

Type of Mining Activity: Underground XX Surface Prep. Plant Other

Officials(s): State: Stephen J. Demczak Company: Mike Glasson

Federal Official(s): Weather Conditions: 30's snow

Existing Acreage: Permitted-3368 Disturbed-34 Regraded-0 Seeded-0 Bonded-34

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NDV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[]	[]	[]	[]
2. SIGNS AND MARKERS	[]	[]	[]	[]
3. TOPSOIL	[]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[]	[XX]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[]	[]	[]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[XX]	[]	[XX]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June)	[]	[]	[]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019 DATE OF INSPECTION: March 11, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

Some of the diversions have been uncovered from snow and were inspected. It was found that maintenance such as resizing and silt removal will be needed for several ditches throughout the property, which are presently uncovered by snow.

4b. Sediment Ponds and Impoundments -

The sediment ponds were snow covered and contained water but were not discharging out of the spillway. Inlet grading maybe required at some of the ponds once snow has melted.

8. Non-coal Waste -

Several areas within the Andalex property need spring time cleaning. There is litter, brattice and containers that need to be cleaned up. Also, the oil storage shed had an oil spill which was contained by a berm. The oil was confined within the storage shed, as designed by the SPCC plan. The spill occurred mostly likely by a tipped over oil container with the lid off. There were no signs of damaged cans. It may be necessary to convey Andalex's company policy on Non-coal Waste to it's employees.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Andalex Resources, Mike Glasson


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: March 18, 1993

Inspector's Signature and Number:


Stephen J. Demczak

#39