


ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860

November 4, 1994



State of Utah
Department of Natural Resources
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attn: Daron Haddock, Permit Supervisor

Re: ACT 007/019 - Drainage Control Plan # 21

Dear Mr. Haddock:

94H
Copy over letters to
immediate file

As a result of heavy precipitation received in October of this year, an erosion problem was observed on a slope below the Aberdeen Seam coal stockpile paid. Andalex has repaired this problem by installing a culvert through the area. We are requesting approval of this action after the fact due to the need for immediate repair.

Enclosed are three (3) copies of the permit change application along with revised certified Plate 8 and certified engineering calculations for culvert sizing.

Thank you very much.

Sincerely,

Michael W. Glasson,
Senior Geologist