



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial: XX Complete: Exploration

Inspection Date/Time: September 12, 1994/07:30am-12:30pm

Date of Last Inspection: August 31, 1994

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019

Permittee and/or Operator's Name: Andalex Resources

Business Address: P. O. Box 902, Price, UT 84501

Type of Mining Activity: Underground XX Surface      Prep. Plant      Other     

Officials(s): State: Stephen J. Demczak Company: Mike Glasson

Federal Official(s):      Weather Conditions: Cool 70's

Existing Acreage: Permitted-5063 Disturbed-34 Regraded-0 Seeded-0 Bonded-34

Increased/Decreased: Permitted-     Disturbed-     Regraded-     Seeded-     Bonded-    

Status: Exploration/ X Active/ Inactive/     Temp Cessation/     Bond Forfeiture

Reclamation (     Phase I/     Phase II/     Final Bond Release/     Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[XX]	[ ]	[XX]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: September 12, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The permittee has shown compliance of the regulation requiring that employees be notified of their rights to contact the Division of environmental harm. The permittee has posted a copy of the regulations requirements on several bulletin boards throughout the mine site.

4a. Diversions -

The diversions were spot checked and showed no signs of erosion or sediment build up.

4c. Other Sediment Control Measures -

The operator was again informed to submit changes to the MRP if it does not comply with the new directive on ASCA and small area exemptions within 30 days of the inspection of August 24, 1994.

5. Explosives -

The permittee has not used explosives on the surfaces since the last inspection check on explosives. The explosives and cap boxes were examined and no problems were noted.


Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Andalex Resources, Mike Glasson Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM) Filed to: Price Field Office

Date: September 27, 1994

Inspector's Signature and Number: 

Stephen J. Demczak

#39