

0017



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

ACT/007/019

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: Complete: X Exploration:
Inspection Date & Time: 5/17/95 8:00am-12:00pm
Date of Last Inspection: 4/18/95

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019
Permittee and/or Operator's Name: Andalex Resources
Business Address: P. O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Mike Glasson
State Officials(s): Stephen J. Demczak Federal Official(s):
Weather Conditions: Cool and Raining
Existing Acreage: Permitted- 5063 Disturbed- 34 Regraded- 0 Seeded- 0 Bonded- 34
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 5/17/95

(Comments are Numbered to Correspond with Topics Listed Above)

**1. PERMIT -**

- a) The insurance accord form was reviewed and was found to be complete and complies with the R645 regulations.
- b) The surface facility and drainage maps were reviewed and compared with actual surface. These maps were correct and no changes will be required.
- c) The NPDES self-monitoring report was reviewed with no discharging occurring for first quarter.
- d) Andalex has submitted an amendment to request power poles within the permit area. This is a small disturbance and will most likely be a small area exemption. No road for installation will be needed.
- e) The sediment ponds were inspected for first quarter with no hazardous conditions reported.

**4A. DIVERSION -**

The diversions were spot-checked throughout the property with some requiring cleaning out due to sediment build-up from the current rain storms. The diversions were stable and no signs of erosion noticed. Operator stated that cleaning of the ditches will take place.

**4B. SEDIMENT PONDS -**

The sediment ponds were inspected with small amounts of water contained within the ponds. It is unlikely that a discharge will occur. Sediment pond C is scheduled for clean out this year. There were no signs of erosion or hazardous conditions.

**4C. OTHER SEDIMENT CONTROL MEASURES -**

The ASCA areas were field reviewed and were performing as designed. The straw bales in several places have been replaced with new ones. The silt has stayed behind the bales.

**5. EXPLOSIVES -**

The explosives containers were checked and being grounded and locked. No new use of explosives has taken place on the surface.

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 11, 1995

Inspector's Signature: \_\_\_\_\_

  
Stephen J. Demczak

#39