



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: ___ Complete: X Exploration: ___
Inspection Date & Time: 2/24/95 7:30am-12:00pm
Date of Last Inspection: 1/19/95

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019
Permittee and/or Operator's Name: Andalex Resources
Business Address: P. O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground XXX Surface ___ Prep. Plant ___ Other ___
Company Official(s): Mike Glasson
State Officials(s): Stephen J. Demczak Federal Official(s):
Weather Conditions: 40's/10" Snow
Existing Acreage: Permitted- 5063 Disturbed- 34 Regraded- 0 Seeded- 0 Bonded- 34
Increased/Decreased: Permitted- ___ Disturbed- ___ Regraded- ___ Seeded- ___ Bonded- ___
Status: ___ Exploration/ XXX Active/ ___ Inactive/ ___ Temporary Cessation/ ___ Bond Forfeiture
Reclamation (___ Phase I/ ___ Phase II/ ___ Final Bond Release/ ___ Liability ___ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 2/24/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

- a) The insurance (expiration date 7/1/75), was reviewed. The accord form met all the requirements of the R645 regulation.
- b) The 4th quarter sediment pond inspections were done on Dec. 30, 1994 with no hazardous conditions existing. The ponds were not discharging. The embankments were covered with snow.
- c) The Annual Pond inspections were completed on Nov. 10, 1994 with no hazardous conditions existing.
- d) The water monitoring was taken on Dec. 30, 1994 with no problems noted. All parameters were taken and timely sent to Lab.
- e) The NPDES self monitoring program report for 4th quarter showed no discharge taking place.
- f) Andalex is going through the mid-term process review by the Division.

4a. DIVERSION -

The diversions were spot-checked with no breaching or overtopping occurring. The ditches have started to fill-up with sediment but do not warrant a violation at this time. The operator will clean diversions once the ground dries out.

b. SEDIMENT PONDS -

The sediment ponds were not discharging during the inspection. The embankments were covered with snow and therefore, no signs of erosion could be seen.

c. OTHER SEDIMENT CONTROL -

Some straw bales could be seen through the snow and it appears that some of these bales will need to be replaced once the snow melts.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:


Mailed to: Mike Glasson (Andalex)

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: March 3, 1995

Inspector's Signature: 

#39