

0011



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

January 24, 1997

Ranvir Singh
Federal Lands Program
Office of Surface Mining
Reclamation and Enforcement
Western Regional Coordinating Center
1999 Broadway, Suite 3320
Denver, CO 80202-5733

Re: Updated List of Violations for Mining Plan, Centennial Mine, Andalex Resources, Inc., ACT/007/019, Folder #2, Carbon County, Utah

Dear Mr. Singh:

I am enclosing an updated list of the violations for the Centennial Mine mining and reclamation plan. This list was submitted as part of the permit renewal for the Centennial Mine, effective January 5, 1997.

Sincerely,

Pamela Grubaugh-Littig
Pamela Grubaugh-Littig
Permit Supervisor

Enclosure


cc: Richard Manus, BLM, Price
Price Field Office

This set can go to your copy
nt.
Brady
Did you send the other ones, too.
Yes. Will do
by.
(about 20 pages)

From
I gave you



**LIST OF VIOLATIONS RECEIVED BY
GENWAL RESOURCES, INC. OPERATIONS 1993-1996**



VIOLATION HISTORY FORMAT KEY:

1. **ISSUING AGENCY**
2. **DATE OF ISSUANCE**
3. **DESCRIPTION OF VIOLATION**
4. **CURRENT STATUS OF PROCEEDINGS**
5. **ACTIONS TAKEN TO ABATE VIOLATION**

-
1. **DOGM**
 2. **N93-43-1-1 was issued on 9/23/93**
 3. **Install 12" cmp without DOGM approval**
 4. **Violation abated on 9/28/93**
 5. **Permit changes submitted and approved**

-
1. **DOGM**
 2. **N95-46-1-1 was issued on 3/9/95**
 3. **Undisturbed diversion pipe was broken**
 4. **Violation abated on 3/17/95**
 5. **Pipe was repaired**

-
1. **DOGM**
 2. **N95-47-1-1 was issued on 8-23-95**
 3. **Sediment pond spillway was above embankment**
 4. **Violation abated on 9/29/95**
 5. **Embankment was built back up**

-
1. **DOGM**
 2. **N96-39-3-1 was issued on 10-17-96**
 3. **Pond clean out spill off of permit area**
 4. **Violation abated on 10/17/96**
 5. **Spill material was removed and area seeded**

-
1. **DOGM**
 2. **N96-39-4-1 was issued on 10/17/96**
 3. **Water monitoring report did not have field & flow measurements**
 4. **Hinderance violation, not abatable**
 5. **No abatement**

007-019 #2




ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860

January 13, 1997

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah, 84114-5801
Attn.: Pamela Grubaugh-Littig



Dear Ms. Littig,

ANDALEX Resources has modified one of its Federal Coal Leases to include a new 160 acre tract adjacent to U-66060. ANDALEX has no specific knowledge that recoverable coal resources exist on this lease modification. However, the Bureau of Land Management (BLM) allowed ANDALEX to modify the lease so that if recoverable coal is found through our normal mining sequence in this area the coal would not be bypassed. ANDALEX has the only access to this reserve if in fact it exists. Now, as ANDALEX approaches this modification, it becomes necessary to include this area as part of ACT 007/019. We have measured the existing mined area on the contiguous ANDALEX leases and find that the modification (160 acres) is considerably less than 15% of the existing disturbed area. Also, the existing CHIA, prepared by the Salt Lake DOGM office should more than adequately cover this small area (please refer to the attached drawing included as Appendix W). At this time ANDALEX is requesting that we be able to cross this boundary by one crosscut (roughly 100 feet). This is our immediate need; the remainder of the lease modification incidental boundary change is needed by September of this year.

Considering these facts, ANDALEX requests that this modification be handled through your Price, Utah office as an Incidental Boundary Change. All of the plates which show the location of this modification have been changed and are attached hereto. Various text changes were also required to include this addition and are included with this submittal.

Please call this office with any questions, as we are needing to proceed onto this modification somewhat sooner than expected. Thank you for your prompt review.

Sincerely,

Michael W. Glasson
Senior Geologist

Enclosure