



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

SW
by
AD

Partial: XXX Complete: Exploration:
Inspection Date & Time: 11:20 AM - 10:40 AM
Date of Last Inspection: 1/31/2001

Mine Name: Centennial Project County: Carbon Permit Number:
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Mr. Mike Glasson, Senior Geologist
State Official(s): Peter Hess Federal Official(s): None
Weather Conditions: Snowing; windy; cold.
Existing Acreage: Permitted 5179.49 Disturbed 35.27 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, TOPSOIL, HYDROLOGIC BALANCE, EXPLOSIVES, DISPOSAL OF EXCESS SPOIL, etc.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/019

DATE OF INSPECTION: 2/28/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

Note: The Centennial site is covered with eight inches of snow and was receiving additional accumulation this morning.

According to Mr. Glasson, approximately 300 feet of longwall pillar remain in the last panel of the Aberdeen Mine. The permittee anticipates the resumption of continuous mining in the Pinnacle Mine by April 1, 2001.

4A. HYDROLOGIC BALANCE: DIVERSIONS

All of the site's ditches which were viewed were filled with accumulations of sidecast snow. All of the culvert inlets/outlets, which were inspected, appeared to be capable of functioning as designed. Snow melt runoff was not observed this day.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

All sediment ponds were snow covered this day; same appeared to be in normal operating condition.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Ms. Karla Knoop is scheduled to initiate water monitoring for the Centennial site for the first quarter of 2001 on March 7.

Inspector's Signature: _____


Peter Hess #46

Date: February 28, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
Mike Glasson, Andalex
Price Field office

O:\007019.CEN\Compliance\2001\p_0228.wpd