



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

Outgoing ^{OK}
c/007/0019 ✓

DIVISION OF OIL, GAS AND MINING FACSIMILE COVER SHEET


DATE: November 20, 2003
FAX #: 1-435-637-8860
ATTN: Mike Glasson
COMPANY: Andalex
DEPARTMENT: _____
NUMBER OF PAGES: (INCLUDING THIS ONE) 2
FROM: Pam

If you do not receive all of the pages, or if they are illegible, please call (801)538-5340. We are sending from a Sharp facsimile machine. Our telecopier number is (801)359-3940.

MESSAGE:
Mike - The cover letter
needs to be revised (as
outlined) ... Would you please
send a corrected letter.
Thank You.

Important: This message is intended for the use of the individual or entity of which it is addressed and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by telephone and return this original message to us at the above address via regular postal service. Thank you.

Pam



ANDALEX
RESOURCES, INC.

PO. BOX 902
PRICE, UTAH 84501
PHONE (435) 637-5385
FAX (435) 637-8860

INCOMING
C0070019

Task ID# 172

October 10, 2003

Utah Division of Oil, Gas and Mining
Coal Program
1594 West North Temple
P.O. Box 145801
Salt Lake City, Utah 84114-5801

Attn: Daron Haddock
Permit Supervisor

Re: Ditch Amendment, Centennial Minesite, C/007/019

OCT 20 2003

Dear Mr. Haddock:

Enclosed are 5 copies of a proposed amendment on disturbed ditch designations at the Centennial Minesite. The amendment is to rectify a discrepancy between the map and on site conditions. Ditches designated DD-5 and ~~DD-10~~ on the Surface Area Drainage Map (Plate 8) have been removed from the map and M.R.P. Ditch DD-5 was shown along the office access road (PR-6); however, due to the narrow road and side slope, there is no ditch along the side. The small amount of runoff here simply flows down the ^{paved} gravel road and goes into a concrete ^{culvert} gutter and to ditch DD-6 and Sediment Pond E. ~~Ditch DD-10 was shown as a small stretch of drainage along the southeast corner of the Pinnacle Mine Stockpile Pad between culverts CD-10 and CD-12. There is no defined ditch at this location, due to the constant changing of the stockpile size; rather, the small amount of drainage travels as overland flow between the stockpile toe and the pad berm, where it leaves the pad through culvert CD-12 to catch Basin B as previously shown. Neither of these changes have any impact on culverts or other hydrologic structures or sizing.~~

***** P. 01 *****

TRANSACTION REPORT NOV-20-2003 THU 11:10 AM

FOR: OIL, GAS & MINING 801 359 3940

DATE START	RECEIVER	TX TIME	PAGES	TYPE	NOTE	M#	DP
NOV-20 11:09 AM	14356378860	45"	2	SEND	OK	729	
TOTAL :					45S PAGES:	2	



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
 Governor
 Robert L. Morgan
 Executive Director
 Lowell P. Braxton
 Division Director

1594 West North Temple, Suite 1210
 PO Box 145801
 Salt Lake City, Utah 84114-5801
 (801) 538-5340 telephone
 (801) 359-3940 fax
 (801) 538-7223 TTY
 www.nr.utah.gov

**DIVISION OF OIL, GAS AND MINING
 FACSIMILE COVER SHEET**

DATE: November 20, 2003

FAX #: 1-435-637-8860

ATTN: Mike Gasson

COMPANY: Endalay

DEPARTMENT: _____

NUMBER OF PAGES: (INCLUDING THIS ONE) 2

FROM: Pam