



Citation for Non-Compliance
Utah Coal Regulatory Program
 1594 West North Temple, Salt Lake City, UT 84114
 Phone: (801) 538-5340 Fax: (801) 359-3940

Citation #: 21197
Permit Number: C0070019
Date Issued: 09/18/2017

NOTICE OF VIOLATION **CESSATION ORDER (CO)** **FAILURE TO ABATE CO**

Permittee Name: ANDALEX RESOURCES INC	Inspector Number and ID: 1 JHELFRIC
Mine Name: CENTENNIAL MINE	Date and Time of Inspection: 08/22/2017 8:00 am
Certified Return Receipt Number: 9590940216186053129574	Date and Time of Service: 09/19/2017 8:00 am

Nature of condition, practice, or violation:
 Based on inspections conducted on 9/20/2016 and 8/22/2017 and Appendix X of the MRP the Division has determined that the permittee has not established a vegetative cover on certain Gob Vent Hole (GVH) sites in accordance with the approved permit and reclamation plan.

Provisions of Act, regulations, or permit violated:
 R645-300-143
 R645-301-353

This order requires Cessation of ALL mining activities. (Check box if appropriate.)

<input type="checkbox"/> Condition, practice, or violation is creating an imminent danger to health or safety of the public.	<input type="checkbox"/> Permittee is/has been conducting mining activities without a Permit.
<input type="checkbox"/> Condition, practice, or violation is causing or can reasonably be expected to cause significant, imminent environmental harm to land, air, or water resources.	<input type="checkbox"/> Permittee has failed to abate Violation(s) included in <input type="checkbox"/> Notice of Violation or <input type="checkbox"/> Cessation Order within time for abatement originally fixed or subsequently extended.

This order requires Cessation of PORTION(S) of mining activities.

Mining activities to be ceased immediately: Yes No **Abatement Times (if applicable).**

Action(s) required: Yes No

Those sites that require fence repairs include but may not be limited to 1, 5, 13, and 17. Sites 5A, 6, 11 and 3 will require fencing unless a variance is specifically authorized by the Division. These actions need to be completed by October 26, 2017. Those sites that require the removal of thistle seed heads include but are not limited to 5A, 6 and 11 and the access road to sites 14 and 8. Thistle seed heads must be removed from the topsoil pile at GVH #6 and the topsoil reseeded. These actions need to be completed by November 30th, 2017. Ongoing thistle control is warranted to ensure the establishment of an adequate vegetative cover.

Karin Madsen

(Print) Permittee Representative

JOE HELFRICH

(Print) DOGM Representative

Permittee Representative's Signature - Date

DOGM Representative's Signature - Date

Joe Helfrich 9/18/2017

SEE REVERSE SIDE OF This Form For Instructions And Additional Information