

0024

March 20, 1996

**EarthFax**

EarthFax  
Engineering Inc.  
Engineers/Scientists  
7324 So. Union Park Ave.  
Suite 100  
Midvale, Utah 84047  
Telephone 801-561-1555  
Fax 801-561-1861

Mr. Sharon Falvey  
Utah Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center  
Salt Lake City, UT 84180-1203

Subject: Data Missing from the Horizon Coal Corporation March 1996 Submittal

Dear Sharon,

*PRO/002/020 #2*

Due to a change in design, Plates 3-2 and 3-7a (cross sections) were not included in the data submitted. Because several calculations are made from these cross sections, the following information is also not correct as it appears in the present submittal.

- Cut and Fill Calculations
- Bond Estimate

Our plan is to have the cross sections, cut and fill calculations, and bond estimate to you by March 28, 1996.

We are also waiting for lab coal data concerning acid-toxic and moisture content, we will include this information as soon as we receive it.

In a letter to the DWR we addressed stipulations in the UDOGM Technical Analysis that the DWR had originally suggested to UDOGM. We sent a copy of this letter to Pam, if you do not have a copy please let me know and I will fax you one.

In our submittal letter we said that Plate 7-8 was missing, however since that time we have eliminated 7-8 and referenced another existing plate in the text.

If you have any questions please call me at (801) 561-1555.

Sincerely yours,

Vicky Bailey, EarthFax