

HIDDEN SPLENDOR RESOURCES, INC.

HORIZON MINE

2006

ANNUAL REPORT

File in:

Confidential

Shelf

Expandable

Refer to Record No. 0009 Date 03/07/06

In CI 0070020 Michigan

For additional information

DOGM PERMIT - C/007/020

2006 ANNUAL REPORT**Page 1**

To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.

GENERAL INFORMATION

Permitte Name HIDDEN SPLENDOR RESOURCES, INC.
 Mine Name HORIZON MINE
 Operator Name _____
 (If other than permittee) _____
 Permit Expiration Date OCTOBER 11, 2011
 Permit Number C/007/020
 Authorized Representative Title KIT PAPPAS - MANAGER OF ENVIRONMENTAL & ENGINEERING
 Phone Number 435-472-0431
 Fax Number 435-472-0439
 E-mail Address kit@emerytelcom.net
 Mailing Address 3266 SOUTH 125 WEST, PRICE, UTAH 84501
 Designated Representative _____
 Resident Agent KIT PAPPAS
 Resident Agent Mailing Address 3266 SOUTH 125 WEST, PRICE, UTAH 84501
 Number of Binders Submitted 2 COPIES (1 BINDER) EACH

IDENTIFICATION OF OTHER PERMITS

Identify other permits that are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expiration Date
MSHA Mine ID(s)	42-02074	HORIZON NO. 1 MINE	N/A
	42-02075	HORIZON NO. 2 MINE (NOT STARTED)	N/A
MSHA Impoundment(s)		NONE	
NPDES/UPDES Permit(s)	UTG040000-001	SEDIMENT POND 001	4/30/2008
	UTG040000-002	PIPE DISCHARGE	4/30/2008
PSD Permit(s) (Air)	DAQE-700-0	MODIFICATION OF APPROVAL ORDER BAQE-336-91	N/A

Other

CERTIFIED REPORTS

List the certified inspection reports as required by the rules and under the approved plan that must be periodically submitted to the Division. Specify whether the information is included as Appendix A to this report or currently on file with the Division.

Certified Reports:	Required		Included or on file with DOGM		Comments
	Yes	No	Included	On File	
Excess Spoil Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Refuse Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

REPORTING OF OTHER TECHNICAL DATA

List other technical data and information as required under the approved plan, which must be periodically submitted to the Division. Specify whether the information is included as Appendix B to this report or currently on file with the Division.

Technical Data:	Required		Included or on file with DOGM		Comments
	Yes	No	Included	On file	
Climatological	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Subsidence Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Vegetation Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Raptor Survey	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Soils Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
First quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Second quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Third quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fourth quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Geological / Geophysical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Engineering	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Non Coal Waste / Abandoned Underground Equipment*	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Other Data					
UNDERGROUND DISCHARGE PUMPING DATA	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
DEER/ELK FATALITY DATA	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
LANDOWNER NOTIFICATION LETTERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

APPENDIX A

Certified Reports

Excess Spoil Piles
Refuse Piles
Impoundments

As required under R645-301-514

CONTENTS

QUARTERLY AND ANNUAL POND INSPECTIONS FOR POND 001
DEQ SITE INSPECTION 4/12/2006

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Page 1 of 1
Permit Number	C/007/020	Report Date: 3-13-2006
Mine Name	Horizon	
Company Name	Hidden Splendor Resources, Inc.	
Impoundment Identification	Impoundment Number	001
	UPDES Permit Number	UTG040019

IMPOUNDMENT INSPECTION

Inspection Date	3-13-2006	
Inspected By	Kit Pappas	
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Annual and Quarterly Inspection	


1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.
 No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.

Required for an impoundment which functions as a SEDIMENTATION POND.

2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.
 60% Sediment Storage – 7566.9
 100 % Sediment Storage – 7569.8

3. Principle and emergency spillway elevations.
 Spillway Elevation - 7573.9 Feet

4. Field Information
 Some water in pond. Frozen over at this time.
 The pond was not discharging at the time of inspection. The inlets and outlet were stable. No instability was noted on the downstream embankment.



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Page 1 of 1
Permit Number	C/007/020	Report Date: 6-21-2006
Mine Name	Horizon	
Company Name	Hidden Splendor Resources, Inc.	
Impoundment Identification	Impoundment Number	001
	UPDES Permit Number	UTG040019

IMPOUNDMENT INSPECTION

Inspection Date	6-20-2006
Inspected By	Kit Pappas
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Quarterly Inspection

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.
 No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.

Required for an impoundment which functions as a SEDIMENTATION POND.

2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.

60% Sediment Storage – 7566.9
 100 % Sediment Storage – 7569.8
 Sediment Elevation @ Waters Edge – 7568.9 @ W. End of Pond – 7570.9

3. Principle and emergency spillway elevations.

Spillway Elevation - 7573.9 Feet

4. Field Information

Small amount of water in pond.
 The pond was not discharging at the time of inspection. The inlets and outlet were stable. No instability was noted on the downstream embankment.
 A pond cleaning plan is being developed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Page 1 of 1
Permit Number	C/007/020	Report Date: 7-26-2006
Mine Name	Horizon	
Company Name	Hidden Splendor Resources, Inc.	
Impoundment Identification	Impoundment Number	001
	UPDES Permit Number	UTG040019

IMPOUNDMENT INSPECTION

Inspection Date	7-26-2006
Inspected By	Kit Pappas
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Quarterly Inspection

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.
 No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.

Required for an impoundment which functions as a SEDIMENTATION POND.	2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment. 60% Sediment Storage – 7566.9 100 % Sediment Storage – 7569.8
	3. Principle and emergency spillway elevations. Spillway Elevation - 7573.9 Feet
	4. Field Information Small amount of water in pond. The pond was not discharging at the time of inspection. The inlets and outlet were stable. No instability was noted on the downstream embankment. The pond sediment was cleaned out from 7-19-06 through 7-21-06. The sediment was placed on the coal storage pad. A 60% capacity marker was placed in the pond on 7-26-06.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Permit Number	C/007/020	Report Date: 10-12-2006
Mine Name	Horizon	
Company Name	Hidden Splendor Resources, Inc.	
Impoundment Identification	Impoundment Number	001
	UPDES Permit Number	UTG040019

IMPOUNDMENT INSPECTION

Inspection Date	10-12-2006
Inspected By	Kit Pappas
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Quarterly Inspection

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.

Required for an impoundment which functions as a SEDIMENTATION POND.**2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.**

60% Sediment Storage - 7566.9
100 % Sediment Storage - 7569.8

3. Principle and emergency spillway elevations.

Spillway Elevation - 7573.9 Feet

4. Field Information

Due to recent heavy rainfall there was a fair amount of water in pond. The pond was not discharging at the time of inspection. The inlets and outlet were stable. No instability was noted on the downstream embankment. The pond sediment was cleaned out from 7-19-06 through 7-21-06. The sediment was placed on the coal storage pad. A 60% capacity marker was placed in the pond on 7-26-06.

*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

GENERAL INFORMATION

Report Date MARCH 7, 2007
 Permit Number C/007/020
 Mine Name HORIZON MINE
 Company Name HIDDEN SPLENDOR RESOURCES, INC.

IMPOUNDMENT IDENTIFICATION

Impoundment Name SEDIMENT POND
 Impoundment Number UTG040000-001
 UPDES Permit Number UTG040000-001
 MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date 10/12/2006, 7/26/2006, 6/21/2006 & 3/13/2006
 Inspected by KIT PAPPAS
 Reason for Inspection QUARTERLY AND ANNUAL
 (Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

- Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

NONE OBSERVED (SEE ACCOMPANYING POND INSPECTION REPORTS)

Questions a and b are required for an impoundment, which functions as a Sedimentation pond.

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

60% ELEVATION - 7566.6, 100% ELEVATION - 7569.8, ESTIMATED AVERAGE ELEVATION OF EXISTING SEDIMENT - 7560

- b. Principle and emergency spillway elevations.

SPILLWAY ELEVATION - 7573.9

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

CURRENT WATER ELEVATION APPROXIMATELY - 7560. POND WAS CLEANED OUT FROM 7-19-06 THROUGH 7-21-06. A 60% CAPACITY MARKER WAS PLACED IN THE POND ON 7-26-06.

COMMENTS/ OTHER INFORMATION

CERTIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.


By: J. T. PALUSO CHIEF ENGINEER - EIS

Full Name and Title

Signature: J. T. Paluso Date 3/6/07

P.E. Number & State 22-150267-2202

[P.E. Cert. Stamp]





State of Utah

Department of
Environmental Quality

Dianne R. Nielson, Ph.D.
Executive Director

DIVISION OF WATER QUALITY
Walter L. Baker, P.E.
Director

JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

April 14, 2006

Mr. Kit Pappas
Hidden Splendor Resources
Mid State Services-Horizon Mine
P.O. Box 32 3266 S. 125 W.
~~Helper, Utah 84526~~ phone, UT 84501-4462

Subject: Reconnaissance Inspection – Horizon Mine

Dear Mr. Pappas:

On April 12, 2006 I conducted a reconnaissance inspection in regards to the Horizon Mine and UPDES Permit No. UTG040019. Specifically I observed the sediment pond, outfall locations and receiving waters of Jewkes Creek.

Enclosed is a copy of the inspection report for your records. If you have any questions, please contact me at (801) 538-6779 or by e-mail at jstudenka@utah.gov.

Sincerely,

Jeff Studenka, Environmental Scientist
UPDES Permits Section

Enclosures

cc (w/encl): Darcy O'Connor, EPA Region VIII
Claron Bjork, SE District Health Department
Dave Ariotti, SE District Engineer
Pam Grubaugh-Littig, Division of Oil Gas & Mines

F:\wp\GP-Coal Mines\HorizonMine\RI2006cov.ltr.doc

NPDES Compliance Inspection Report

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspection Type	Inspector	Fac Type			
1 <u>N</u>	2 <u>U</u>	3 <u>U T G 0 4 0 0 1 9</u>	11	12 <u>06 04 12</u>	17	18 <u>R</u>	19 <u>S</u>	20 <u>L</u>
Remarks								
21	Reserved					66		
67	70 <u>L</u>	71 <u>N</u>	72 <u>N</u>	73	75	80		

Section B: Facility Data

Name and Location of Facility Inspected HIDDEN SPLENDOR RESOURECES-HORIZON MINE COUNTY ROAD 290 (CONSUMER'S ROAD), HELPER, UT		Entry Time/Date 4:00 pm 4-12-06	Permit Effective Date 05-01-2003
		Exit Time/Date 4:15 pm 4-12-06	Permit Expiration Date 04-30-2008
Name(s) of On-Site Representative(s) N/A		Title(s) N/A	Phone No(s) N/A
Name, Address of Responsible Official Kit Pappas MID-STATE SERVCIES P.O. Box 32 3266 S. 125 W. Helper, UT 84526 Price, UT 84501-4462		Title Environmental Coordinator	Phone No. 435-472-0431
		Contacted No	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated, NA = Not Applicable)

S	Permit	N	Flow Measurement	NA	Pretreatment	S	Operations & Maintenance
S	Records/Reports	N	Laboratory	NA	Compliance Schedules	NA	Sludge Disposal
	Facility Site Review	S	Effluent/Receiving Water	S	Self-Monitoring Program		Other:

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

The purpose for the site visit was to perform a reconnaissance inspection while already in the area. A tour of the site included observing the two outfall locations and sediment pond followed by the receiving waters of Jewkes Creek. This is an active coal mining site that discharges mine water to Jewkes Creek at outfall 002. The sediment pond however, has not discharged from outfall 001 in several years and will not likely discharge in the foreseeable future. There were no deficiencies observed during the inspection.

Name(s) and Signature(s) of Inspector(s) JEFF STUDENKA <i>Jeff Studenka</i>	Agency/Office/Telephone (801) 538-6779 DIVISION OF WATER QUALITY	Date 4-14-06
N/A	Agency/Office/Telephone N/A	Date N/A
Signature of Reviewer MIKE HERKIMER, MANAGER NPDES PERMITS SECTION <i>Mike Herkimer</i>	Agency/Office (801) 538-6058 DIVISION OF WATER QUALITY	Date 4/14/06

Regulatory Office Use Only

Inspection Taken	Date	Compliance Status Noncompliance Compliance
------------------	------	--

APPENDIX B

Reporting of Technical Data

Including monitoring data, reports, maps, and other information
As required under the approved plan or as required by the Division


In accordance with the requirement of R645-310-130 and R645-301-140

CONTENTS

SUBSIDENCE MONITORING SURVEY
UNDERGROUND DISCHARGE PUMPING DATA
BIG GAME ROAD KILL FATALITY REPORT


MID STATE SERVICES, INC.
HORIZON MINE SUBSIDENCE SURVEY

STATION	NORTHING	EASTING	ELEVATION	DESCRIPTION
CALIBRATION CONTROL				
A	497114.12	2122250.60	8655.40	rebar
NW 20	494001.85	2124908.62	7754.23	Brass Cap
MEASURED	Oct. 2006			
SP4	498315.92	2124251.96	8039.45	5/8" rebar w/cap
SP9	499712.95	2119668.78	8546.30	5/8" rebar w/cap
SUB1	499817.08	2122414.02	8456.98	5/8" rebar w/cap
SUB2	500025.38	2123687.85	8414.59	5/8" rebar w/cap
SUB3	500318.48	2124538.01	8389.45	5/8" rebar w/cap
SUB4	500883.63	2125415.20	8360.96	5/8" rebar w/cap
SUB5	501926.97	2126811.98	8315.97	5/8" rebar w/cap
SUB6	501496.20	2128478.51	8708.14	5/8" rebar w/cap
SUB7	500140.95	2128310.25	8838.62	5/8" rebar w/cap



WARE SURVEYING & ENGINEERING

G.P.S. & CONVENTIONAL SURVEYING - AUTOCAD MAPPING - CIVIL ENGINEERING



Big Game Road Kill Fatality Report

Year	1st Quarter		2nd Quarter		3rd Quarter		4th Quarter		Total
	Employee Killed	Other Killed							
1997									
Deer	0	0	0	0	0	0	0	0	0
Elk	0	0	0	0	0	0	0	0	0
1998									
Deer	0	0	0	0	0	0	0	0	0
Elk	0	0	0	0	0	0	0	0	0
1999									
Deer	0	0	0	0	0	0	0	0	0
Elk	0	0	0	0	0	0	0	0	0
2000									
Deer	0	0	0	0	0	0	0	2	2
Elk	0	0	0	0	0	0	0	0	0
2001									
Deer	1	0	0	0	0	0	0	0	1
Elk	0	0	0	0	0	0	0	0	0
2002									
Deer	0	0	0	0	0	0	0	0	0
Elk	0	0	0	0	0	0	0	0	0
2003									
Deer	0	0	0	0	0	0	0	0	0
Elk	0	0	0	0	0	0	0	0	0
2004									
Deer	0	1	1	0	0	0	0	1	3
Elk	0	0	0	0	0	0	0	0	0
2005									
Deer	0	2	1	0	0	0	0	2	5
Elk	0	0	0	0	0	0	0	0	0
2006									
Deer	0	0	0	0	0	0	0	0	0
Elk	0	0	0	0	0	0	0	0	0

* - Totals verified by Derris Jones - DWR (Habitat Manager) 11/08/00

APPENDIX C

Legal Financial, Compliance and Related Information

Annual Report of Officers
As submitted to the Utah Department of Commerce

Other change in ownership and control information
As required under R645-301-110

CONTENTS

APPENDIX D

Mine Maps

As required under R645-302-525-270

CONTENTS

HORIZON MINE 2006 MINING & 5 YEAR MINE PLAN

APPENDIX E

Other Information

In accordance with the requirements of R645-301 and R645-302

CONTENTS

DEQ WATER ANALYSES
HORIZON WELL MONITORING DATA
LANDOWNER NOTIFICATION LETTERS



JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

State of Utah

Department of Environmental Quality
Division of Water Quality

Dianne R. Nielson, Ph.D.
Executive Director

Walter L. Baker, P.E.
Director

Kit Pappas
Hidden Splendor Resources-Horizon Mine
3266 South 125 West
Price UT 84501

RE: Compliance Monitoring - UTG040019
3/17/2006

The Utah Division of Water Quality grab sampled your wastewater discharge, Storet No. 4931520 (LOADSTAR HORIZON COAL 002 MINE WATER) on 2/7/2006 and obtained the following results.

	<u>Value</u>	<u>UOM</u>	<u>Fraction</u>	<u>Limit</u>	<u>UOM</u>
Field Tests					
Dissolved oxygen (DO)	7	mg/l	Total	()	()
Dissolved oxygen saturation	69.4	%	Total	()	()
Flow	700	gal/min		()	()
Salinity	0.3	ppt	Total	()	()
Specific conductance	596.3	umho/cm		()	()
Temperature, water	8.98	deg C		()	()
pH	8.22	None	Total	()	()
Laboratory Analysis					
Iron	0.158	mg/l	Total	()	()
Solids, Dissolved	348	mg/l		()	()
Solids, Total Suspended (TSS)	5.6	mg/l		()	()

For your information the values for those parameters checked (X) appear to exceed your permit limits.

Sincerely,

Jeff Studenka
Environmental Scientist
Permits & Compliance Section
Division of Water Quality



JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

State of Utah

Department of Environmental Quality
Division of Water Quality

Dianne R. Nielson, Ph.D.
Executive Director

Walter L. Baker, P.E.
Director

Kit Pappas
Hidden Splendor Resources-Horizon Mine
3266 South 125 West
Price UT 84501

RE: Compliance Monitoring - UTG040019
5/2/2006

The Utah Division of Water Quality grab sampled your wastewater discharge, Storet No. 4931520 (LOADSTAR HORIZON COAL 002 MINE WATER) on 3/28/2006 and obtained the following results.

	<u>Value</u>	<u>UOM</u>	<u>Fraction</u>	<u>Limit</u>	<u>UOM</u>
Field Tests					
Dissolved oxygen (DO)	7.96	mg/l	Total	()	()
Dissolved oxygen saturation	85.4	%	Total	()	()
Flow	500	gal/min		()	()
Salinity	0.31	ppt	Total	()	()
Specific conductance	615	umho/cm		()	()
Temperature, water	11.8	deg C		()	()
pH	7.88	None	Total	()	()
Laboratory Analysis					
Iron	0.216	mg/l	Total	()	()
Solids, Dissolved	352	mg/l		()	()
Solids, Total Suspended (TSS)	20.7	mg/l		()	()

For your information the values for those parameters checked (X) appear to exceed your permit limits.

Sincerely,

Jeff Studenka
Environmental Scientist
Permits & Compliance Section
Division of Water Quality



JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

State of Utah

Department of Environmental Quality
Division of Water Quality

Dianne R. Nielson, Ph.D. Walter L. Baker, P.E.
Executive Director Director

Kit Pappas
Hidden Splendor Resources-Horizon Mine
3266 South 125 West
Price UT 84501

RE: Compliance Monitoring - UTG040019
9/18/2006

The Utah Division of Water Quality grab sampled your wastewater discharge, Storet No. 4931520 (LOADSTAR HORIZON COAL 002 MINE WATER) on 6/20/2006 and obtained the following results.

	<u>Value</u>	<u>UOM</u>	<u>Fraction</u>	<u>Limit</u>	<u>UOM</u>
Field Tests					
Dissolved oxygen (DO)	8.16	mg/l	Total	()	()
Dissolved oxygen saturation	91.1	%	Total	()	()
Flow	450	gal/min		()	()
Salinity	0.31	ppt	Total	()	()
Specific conductance	607	umho/cm		()	()
Temperature, water	13.4	deg C		()	()
pH	7.95	None	Total	()	()
Laboratory Analysis					
Iron	0.1	mg/l	Total	()	()
Solids, Dissolved	362	mg/l		()	()
Solids, Total Suspended (TSS)	6.4	mg/l		()	()

For your information the values for those parameters checked (X) appear to exceed your permit limits.

Sincerely,

Jeff Studenka
Environmental Scientist
Permits & Compliance Section
Division of Water Quality



JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

State of Utah

Department of Environmental Quality
Division of Water Quality

Dianne R. Nielson, Ph.D. Walter L. Baker, P.E.
Executive Director Director

Kit Pappas
Hidden Splendor Resources-Horizon Mine
3266 South 125 West
Price UT 84501

RE: Compliance Monitoring - UTG040019
12/8/2006

The Utah Division of Water Quality grab sampled your wastewater discharge, Storet No. 4931520 (LOADSTAR HORIZON COAL 002 MINE WATER) on 10/31/2006 and obtained the following results.

	<u>Value</u>	<u>UOM</u>	<u>Fraction</u>	<u>Limit</u>	<u>UOM</u>
Tests					
Dissolved oxygen (DO)	7.56	mg/l	Total	()	()
Dissolved oxygen saturation	82.4	%	Total	()	()
Salinity	0.19	ppt	Total	()	()
Specific conductance	379	umho/cm		()	()
Temperature, water	12.15	deg C		()	()
pH	7.73	None	Total	()	()
Laboratory Analysis					
Iron	0.134	mg/l	Total	()	()
Solids, Dissolved	334	mg/l		()	()
Solids, Total Suspended (TSS)	16	mg/l		()	()

For your information the values for those parameters checked (X) appear to exceed your permit limits.

Sincerely,

Jeff Studenka
Environmental Scientist
Permits & Compliance Section
Division of Water Quality

TABLE 7-1 (Continued)

WATER-LEVEL DATA OBTAINED FROM
LOCAL MONITORING WELLS

Date	HZ-95-1		HZ-95-1S		HZ-95-2		HZ-95-3		HZ-01-06-1	
	Depth (ft)*	Elevation (ft)								
12/5/95	--	--	135.0	8221.5	828.0	7519.6	--	--		
12/13/95	786.00	7570.70	--	--	--	--	--	--		
12/21/95	--	--	--	--	--	--	378.80	7522.70		
7/9-10/96	711.30	7585.40	133.80	8222.70	830.00	7517.60	380.80	7520.70		
8/5/96	770.80	7585.90	133.50	8223.00	829.40	7518.20	387.80	7513.70		
9/11/96	769.40	7587.30	132.50	8224.00	829.40	7518.20	387.70	7513.80		
10/23/96	776.40	7580.30	132.50	8224.00	829.20	7518.40	380.70	7520.80		
11/1/96	776.40	7580.30	132.50	8224.00	829.20	7518.40	380.80	7520.70		
12/13/96	#		#		829.50	7518.10	379.50	7522.00		
1/6/97	771.05	7584.75	133.00	8223.50						
2/10/97	+		+		+		+			
3/25/97	+		+		+		+			
4/1/97	+		+		+		+			
5/28/97	770.95	7584.90	131.50	8225.10	828.05	7519.55	379.90	7522.40		
6/30/97	770.20	7585.60	132.14	8224.36	827.72	7519.88	379.90	7522.40		
9/16/97	773.50	7583.90	132.50	8224.00	827.20	7520.40	379.90	7522.40		
10/17/97	773.70	7583.70	132.50	8224.00	827.20	7520.40	379.90	7522.40		
6/30/98	817.80	7538.90	133.10	8223.40	836.60	7511.00	395.10	7506.40		
9/1/98	745.00	7611.70	134.50	8222.00	840.90	7506.70	398.00	7503.50		
6/1/99	758.80	7597.90	133.70	8222.80	847.80	7499.80	399.50	7502.00		
7/1/99	758.10	7598.60	134.40	8222.10	845.90	7501.70				
11/1/99	+		+		+		397.00	7504.50		
5/20/00	862.70	7494.00	132.80	8223.70	849.80	7497.80	401.50	7500.00		
9/8/00							402.10	7499.40		
9/26/00	875.00	7481.70	134.40	8222.10	863.80	7483.80				
10-12/31/00	\$		\$		\$		\$			
12/12/00	+		+		+		+			
3/23/01	+		+		+		+			
5/31-6/1/01	870.55	7486.15	133.75	8222.75	856.75	7490.85	414.17	7487.33		
9/20/01	876.85	7479.85	134.50	8222.00	862.40	7485.20	416.10	7485.40		
10/19/01	873.36	7483.34	134.65	8221.85	858.71	7488.89	415.70	7485.80		
11/17/01									944.20	7817.20
2/18/02	@		@		@		@		@	
3/25/02	@		@		@		@		@	
6/12/02	876.68	7480.02	135.08	8221.42	867.38	7480.22	458.12	7443.38	1029.58	7731.82
9/4/02	876.85	7479.85	136.37	8220.13	869.28	7478.32	%465.1	%7436.4	1036.85	7724.55
10/8/02	876.55	7480.15	136.00	8220.50	869.65	7477.95	%465.1	%7436.4	1037.45	7723.95
5/14/03	@		@		@		%465.1	%7436.4	@	
5/28/03	875.12	7481.38	135.35	8221.15	872.00	7475.60	%465.1	%7436.4	1036.6	7724.80
9/5/03	876.22	7480.48	135.51	8220.99	871.73	7475.87	%465.1	%7436.4	1036.74	7724.66
10/16/03	876.24	7480.46	135.45	8220.93	871.92	7476.06	%465.1	%7436.4	1036.5	7724.46
3/1/04	@		@		@				@	
3/29/04	@		@		@		%465.1	%7436.4		
6/18/04	901.54	7455.16	135.68	8220.82	877.20	7470.40	%465.1	%7436.4	1062.50	7698.90
9/27/04	905.72	7450.98	136.15	8220.35	878.00	7469.60	%465.1	%7436.4	1050.55	7710.85
10/14/04	909.25	7447.45	135.90	8220.60	878.17	7469.43	%465.1	%7436.4	1050.33	7711.07
3/16/05	@		@		@		@		@	
3/31/05	@		@		@		@		@	
6/28/05	993.51	7363.19	132.90	8223.70	882.62	7464.98	%465.1	%7436.4	1039.76	7721.64
9/22/05	993.67	7363.03	133.90	8222.60	844.50	7503.10	%465.1	%7436.4	1039.91	7721.49
10/13/05	993.61	7363.09	135.82	8211.78	844.61	7502.99	%465.1	%7436.4	1039.80	7721.60
3/31/06	@		@		@		@		@	
6/23/06	999.13	7357.60	143.61	8212.90	887.24	7460.40	%465.1	%7436.4	1039.20	7722.20

Hidden Splendor Resources
Horizon Mine
P.O. Box 32
Helper, Utah 84526
Phone: 435-472-1313 Fax: 435-472-1314

March 21, 2005

Arthur J. Anderson, Et al
4190 Fortuna Way
Salt Lake City, Utah 84117

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

Re: Horizon Mine
DOGM Permit # C/007/0020

Dear Mr. Anderson Et al:

Hidden Splendor Resources, Inc., Horizon Mine, is required under Utah Division of Oil, Gas & Mining Regulation R645-301-500.700, to provide written noticed to surface landowners within the permit area.

Hidden Splendor Resources, Inc. is currently the leaseholder of Federal Coal Lease #U-74804 and is currently operating the Horizon underground mine in the above-mentioned lease.

Hidden Splendor Resources, Inc., Horizon Mine, may or may not conduct underground mining activities beneath your property in the future.

Hidden Splendor Resources, Inc. does not anticipate any adverse effects to your property, nor plans any surface disturbance to your property because of its underground mining operation.

The description of your surface property within the permit area is as follows:

N1/2 NE1/4 Section 7, Township 13 South, Range 8 East, SLBM
SW1/4 NE1/4 Section 7, Township 13 South, Range 8 East, SLBM
NW1/4 NW1/4 Section 8, Township 13 South, Range 8 East, SLBM

Copies of Hidden Splendor Resources, Inc. subsidence plan are located at the Division of Oil, Gas & Mining Office, 1594 West North Temple, Suite 1210, Salt Lake City, Utah 84114-5801,

or at the Division of Oil, Gas & Mining, Price Field Office, 455 West Railroad Avenue, Price,
Utah 84501.

Should you have any questions or comments, please feel free to contact me at 435-472-0431.



Kit Pappas
Engineering/Environmental

Cc: File

7004 2510 0005 4739 3499

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

SAINT LAKE CITY, UT 84117 **OFFICIAL USE**

Postage	\$ 0.37	UNIT ID: 0501 Postmark Here Clerk: KY39H7 03/21/05
Certified Fee	2.30	
Return Receipt Fee (Endorsement Required)	1.75	
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$ 4.42	

Sent To ANDERSON
 Street, Apt. No.,
 or PO Box No. 4790 FORTUNA WAY
 City, State, ZIP+4 SALT LAKE CITY UT 84117

PS Form 3800, June 2002 See Reverse for Instructions

Hidden Splendor Resources
Horizon Mine
P.O. Box 32
Helper, Utah 84526
Phone: 435-472-1313 Fax: 435-472-1314

March 21, 2005

L& E BROWN FAMILY, LC
65 EAST 400 SOUTH
OREM, UTAH 84058

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

Re: Horizon Mine
DOGM Permit # C/007/0020

Dear Brown Family:

Hidden Splendor Resources, Inc., Horizon Mine, is required under Utah Division of Oil, Gas & Mining Regulation R645-301-500.700, to provide written notice to surface landowners within the permit area.

Hidden Splendor Resources, Inc. is currently the leaseholder of Federal Coal Lease #U-74804 and is currently operating the Horizon underground mine in the above-mentioned lease.

Hidden Splendor Resources, Inc., Horizon Mine, may or may not conduct underground mining activities beneath your property in the future.

Hidden Splendor Resources, Inc. does not anticipate any adverse effects to your property, nor plans any surface disturbance to your property because of its underground mining operation.

The description of your surface property adjacent to the permit area is as follows:

Section 1, Township 13 South, Range 8 East, SLBM
Section 12, Township 13 South, Range 8 East, SLBM

Copies of Hidden Splendor Resources, Inc. subsidence plan are located at the Division of Oil, Gas & Mining Office, 1594 West North Temple, Suite 1210, Salt Lake City, Utah 84114-5801, or at the Division of Oil, Gas & Mining, Price Field Office, 455 West Railroad Avenue, Price, Utah 84501.

Should you have any questions or comments, please feel free to contact me at 435-472-0431.

Sincerely,

A handwritten signature in black ink, appearing to read "Kit Pappas". The signature is written in a cursive, flowing style.

Kit Pappas
Engineering/Environmental

Cc: File

7004 2510 0005 4739 3635

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OREM, UT 84058 OFFICIAL USE

Postage	\$ 0.37	UNIT ID: 0501 Postmark Here Clerk: KY39H7 03/21/05
Certified Fee	2.30	
Return Receipt Fee (Endorsement Required)	1.75	
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$ 4.42	

Sent To *Brown*

Street, Apt. No., or PO Box No. *65 E. 400 S.*

City, State, ZIP+4 *OREM, UT 84058*

Hidden Splendor Resources
Horizon Mine
P.O. Box 32
Helper, Utah 84526
Phone: 435-472-1313 Fax: 435-472-1314

March 21, 2005

Roy M. Farley
Tess Farley
C/O Farley Management
4807 South Wallace Lane
Holiday, Utah 84117

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

Re: Horizon Mine
DOGM Permit # C/007/0020

Dear Mr. and Mrs. Farley:

Hidden Splendor Resources, Inc., Horizon Mine, is required under Utah Division of Oil, Gas & Mining Regulation R645-301-500.700, to provide written notice to surface landowners within the permit area.

Hidden Splendor Resources, Inc. is currently the leaseholder of Federal Coal Lease #U-74804 and is currently operating the Horizon underground mine in the above-mentioned lease.

Hidden Splendor Resources, Inc., Horizon Mine, may or may not conduct underground mining activities beneath your property in the future.

Hidden Splendor Resources, Inc. does not anticipate any adverse effects to your property, nor plans any surface disturbance to your property because of its underground mining operation.

The description of your surface property within the permit area is as follows:

SW1/4 SW1/4 Section 8, Township 13 South, Range 8 East, SLBM
NW1/4 NW1/4 Section 17, Township 13 South, Range 8 East, SLBM

Copies of Hidden Splendor Resources, Inc. subsidence plan are located at the Division of Oil, Gas & Mining Office, 1594 West North Temple, Suite 1210, Salt Lake City, Utah 84114-5801,

or at the Division of Oil, Gas & Mining, Price Field Office, 455 West Railroad Avenue, Price,
Utah 84501.

Should you have any questions or comments, please feel free to contact me at 435-472-0431.



Kit Pappas
Engineering/Environmental

Cc: File

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

SALT LAKE CITY, UT 84117

ORIGINAL USE

Postage	\$ 0.37	UNIT ID: 0501 Postmark Here Clerk: KY39H7 03/21/05
Certified Fee	2.30	
Return Receipt Fee (Endorsement Required)	1.75	
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$ 4.42	

Sent To FARLEY
 Street, Apt. No.,
 or PO Box No. 4807 S WALLACE LN
 City, State, ZIP+4 HOLIDAY, UT 84117

PS Form 3800, June 2002 See Reverse for Instructions

7004 2510 0005 4739 3642

Hidden Splendor Resources
Horizon Mine
P.O. Box 32
Helper, Utah 84526
Phone: 435-472-1313 Fax: 435-472-1314

March 21, 2005

James C. Jacob
J. Mark Jacob
914 East 300 North
Orem, Utah 84097-5096

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

Re: Horizon Mine
DOGM Permit # C/007/0020

Dear Mr. Jacob:

Hidden Splendor Resources, Inc., Horizon Mine, is required under Utah Division of Oil, Gas & Mining Regulation R645-301-500.700, to provide written noticed to surface landowners within the permit area.

Hidden Splendor Resources, Inc. is currently the leaseholder of Federal Coal Lease #U-74804 and is currently operating the Horizon underground mine in the above-mentioned lease.

Hidden Splendor Resources, Inc., Horizon Mine, may or may not conduct underground mining activities beneath your property in the future.

Hidden Splendor Resources, Inc. does not anticipate any adverse effects to your property, nor plans any surface disturbance to your property because of its underground mining operation..

The description of your surface property within the permit area is as follows:

SW1/4 NW1/4 Section 17, Township 13 South, Range 8 East, SLBM
NW1/4 NE1/4 Section 17, Township 13 South, Range 8 East, SLBM
NE1/4 NE1/4 Section 18, Township 13 South, Range 8 East, SLBM

Copies of Hidden Splendor Resources, Inc. subsidence plan are located at the Division of Oil, Gas & Mining Office, 1594 West North Temple, Suite 1210, Salt Lake City, Utah 84114-5801,

or at the Division of Oil, Gas & Mining, Price Field Office, 455 West Railroad Avenue, Price,
Utah 84501.

Should you have any questions or comments, please feel free to contact me at 435-472-0431.

Sincerely,

A handwritten signature in cursive script, appearing to read "Kit Pappas".

Kit Pappas
Engineering/Environmental

Cc: File

7004 2510 0005 4739 3482

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OREM, UT 84097

Postage	\$ 0.37	UNIT ID: 0501 Postmark Here Clerk: KY39H7 03/21/05
Certified Fee	2.30	
Return Receipt Fee (Endorsement Required)	1.75	
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$ 4.42	

Sent To JACOBS

Street, Apt. No., or PO Box No. 914 E. 300 N

City, State, ZIP+4 OREM, UT 84097-5096

Hidden Splendor Resources
Horizon Mine
P.O. Box 32
Helper, Utah 84526
Phone: 435-472-1313 Fax: 435-472-1314

March 21, 2005

Mr. Pete Stamatakis
1111 South 450 West
Carbonville, Utah 84501

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

Re: Horizon Mine
DOGM Permit # C/007/0020

Dear Mr. Stamatakis:

Hidden Splendor Resources, Inc., Horizon Mine, is required under Utah Division of Oil, Gas & Mining Regulation R645-301-500.700, to provide written notice to surface landowners within the permit area.

Hidden Splendor Resources, Inc. is currently the leaseholder of Federal Coal Lease #U-74804 and is currently operating the Horizon underground mine in the above-mentioned lease.

Hidden Splendor Resources, Inc., Horizon Mine, may or may not conduct underground mining activities beneath your property in the future.

Hidden Splendor Resources, Inc. does not anticipate any adverse effects to your property, nor plans any surface disturbance to your property because of its underground mining operation.

The description of your surface property within the permit area is as follows:

SE1/4 SW1/4 Section 6, Township 13 South, Range 8 East, SLBM
W1/2 SE1/4 Section 6, Township 13 South, Range 8 East, SLBM
SE1/4 SE1/4 Section 6, Township 13 South, Range 8 East, SLBM
NW1/4 Section 7, Township 13 South, Range 8 East, SLBM
N1/2 SW1/4 Section 7, Township 13 South, Range 8 East, SLBM
SE1/4 SW1/4 Section 7, Township 13 South, Range 8 East, SLBM
SE1/4 Section 7, Township 13 South, Range 8 East, SLBM

SE1/4 NE1/4 Section 7, Township 13 South, Range 8 East, SLBM
S1/2 NW1/4 Section 8, Township 13 South, Range 8 East, SLBM
SW1/4 NE1/4 Section 8, Township 13 South, Range 8 East, SLBM
N1/2 SW1/4 Section 8, Township 13 South, Range 8 East, SLBM
NW1/4 SE1/4 Section 8, Township 13 South, Range 8 East, SLBM
NE1/4 NE1/4 Section 18, Township 13 South, Range 8 East, SLBM

Copies of Hidden Splendor Resources, Inc. subsidence plan are located at the Division of Oil, Gas & Mining Office, 1594 West North Temple, Suite 1210, Salt Lake City, Utah 84114-5801, or at the Division of Oil, Gas & Mining, Price Field Office, 455 West Railroad Avenue, Price, Utah 84501.

Should you have any questions or comments, please feel free to contact me at 435-472-0431.



Kit Pappas
Engineering/Environmental

Cc: File

7004 2510 0005 4739 3505

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

PRICE UT 84501

Postage	\$ 0.37
Certified Fee	2.30
Return Receipt Fee (Endorsement Required)	1.75
Restricted Delivery Fee (Endorsement Required)	
Total Postage & Fees	\$ 4.42

UNIT ID: 0501
Postmark Here
Clerk: KY39H7
03/21/05

Sent To P. SAMATAKIS

Street, Apt. No.,
or PO Box No. 1111 S. 950 W.

City, State, ZIP+4 PRICE UT 84501

Hidden Splendor Resources
Horizon Mine
P.O. Box 32
Helper, Utah 84526
Phone: 435-472-1313 Fax: 435-472-1314

March 21, 2005

Mr. Steve Stamatakis
2676 West Gordon Creek Road
Carbonville, Utah 84501

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

Re: Horizon Mine
DOGM Permit # C/007/0020

Dear Mr. Stamatakis:

Hidden Splendor Resources, Inc., Horizon Mine, is required under Utah Division of Oil, Gas & Mining Regulation R645-301-500.700, to provide written notice to surface landowners within the permit area.

Hidden Splendor Resources, Inc. is currently the leaseholder of Federal Coal Lease #U-74804 and is currently operating the Horizon underground mine in the above-mentioned lease.

Hidden Splendor Resources, Inc., Horizon Mine, may or may not conduct underground mining activities beneath your property in the future.

Hidden Splendor Resources, Inc. does not anticipate any adverse effects to your property, nor plans any surface disturbance to your property because of its underground mining operation.

The description of your surface property within the permit area is as follows:

SE1/4 SW1/4 Section 6, Township 13 South, Range 8 East, SLBM
W1/2 SE1/4 Section 6, Township 13 South, Range 8 East, SLBM
SE1/4 SE1/4 Section 6, Township 13 South, Range 8 East, SLBM
NW1/4 Section 7, Township 13 South, Range 8 East, SLBM
N1/2 SW1/4 Section 7, Township 13 South, Range 8 East, SLBM
SE1/4 SW1/4 Section 7, Township 13 South, Range 8 East, SLBM
SE1/4 Section 7, Township 13 South, Range 8 East, SLBM

SE1/4 NE1/4 Section 7, Township 13 South, Range 8 East, SLBM
S1/2 NW1/4 Section 8, Township 13 South, Range 8 East, SLBM
SW1/4 NE1/4 Section 8, Township 13 South, Range 8 East, SLBM
N1/2 SW1/4 Section 8, Township 13 South, Range 8 East, SLBM
NW1/4 SE1/4 Section 8, Township 13 South, Range 8 East, SLBM
NE1/4 NE1/4 Section 18, Township 13 South, Range 8 East, SLBM

Copies of Hidden Splendor Resources, Inc. subsidence plan are located at the Division of Oil, Gas & Mining Office, 1594 West North Temple, Suite 1210, Salt Lake City, Utah 84114-5801, or at the Division of Oil, Gas & Mining, Price Field Office, 455 West Railroad Avenue, Price, Utah 84501.

Should you have any questions or comments, please feel free to contact me at 435-472-0431.



Kit Pappas
Engineering/Environmental

Cc: File

7004 2510 0005 4739 3512

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

PRICE, UT 84501

Postage	\$ 0.37	UNIT ID: 0501
Certified Fee	2.30	
Return Receipt Fee (Endorsement Required)	1.75	
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$ 4.42	Postmark Here Clerk: KY39H7 03/21/05

Sent To G. STAMATAKIS
 Street, Apt. No. or PO Box No. 7676 W. GARDEN CREEK RD.
 City, State, ZIP+4 CARBONVILLE UT 84501

PS Form 3800, June 2002 See Reverse for Instructions