



**Action Taken on Existing Citation
Utah Coal Regulatory Program**

1594 West North Temple, Salt Lake City, UT 84114
Phone: (801) 538 - 5285 Fax: (801) 359-3940

Action on Citation#: **10141**
Permit Number: **C0070020**
Date Cit. Issued: **05/27/2014**

<input checked="" type="checkbox"/> MODIFICATION of	<input type="checkbox"/> TERMINATION of	<input type="checkbox"/> VACATION of
<input checked="" type="checkbox"/> NOTICE OF VIOLATION	<input type="checkbox"/> CESSATION ORDER (CO)	<input type="checkbox"/> FAILURE TO ABATE CO

Permittee Name: HIDDEN SPLENDOR RESOURCES	Inspector Number and ID: 67 ADANIELS
Mine Name: HORIZON MINE	Date and Time of Action:
Certified Return Receipt Number:	Date and Time of Service:

In accordance with the provisions of the Utah Coal Mining and Reclamation Act, Utah Code Ann. § 40-10-1 et. seq. (Act), the above referenced Citation is:

Modified as follows:
 Actions Required:
 (1) The Permittee must repair the sediment pond and associated features (i.e. decant pipe, inlets) to meet the approved design specifications in the MRP.
 (2) Provide a Professional Engineer (P.E.) certified survey report indicating the elevation of the sediment level in the pond. If the survey data indicates the sediment level is above the clean-out, as detailed in the MRP, the Permittee must remove the accumulated material from the pond. As the sediment level of the pond is now in question, a professional survey is now required. All of the work sited above must be completed by August 4, 2014.
Reason for modification:
 A 30 day extension was requested by the operator.

Terminated because:

Vacated because:

ALEX WALKER (Print) Permittee Representative	AMANDA DANIELS (Print) DOGM Representative
_____ Permittee Representative's Signature - Date	_____ DOGM Representative's Signature - Date

Refer to the "Citation For Non-Compliance" for additional information