

November 10, 1982

Inspection Memo
to Coal File:

RE: Blazon Company
Blazon Mine
ACT/007/021
Carbon County, Utah

An inspection of the Blazon Mine was conducted on October 21, 1982 by Doug Maier and Sandy Pruitt. There was no one present on-site and no evidence of recent activity other than vehicular access.

Maintenance of runoff control structures (berms and ditches) over the entire mine yard is necessary for compliance with UMC 817.42(a)(1) and UMC 817.45. The berm all along Mud Creek should be reconstructed to contain disturbed area runoff on-site. Spillage consisting of waste rock refuse on the creek embankments above the upper cross culvert should be retrieved and disposed of properly in the fill.

These compliance measures should be completed before the next inspection or violations will be warranted.

SANDY PRUITT *SP*
FIELD SPECIALIST

cc: Tom Ehmett, OSM
Allen Smith, North American Equities (RRRR)
Inspection Staff

SP/btb

Statistics:

See Gordon Creek #3 & 6 Mines memo dated November 1, 1982
Grant: A & E