

November 28, 1984

TO: Coal File, Inspection and Enforcement
FROM: Sandy Pruitt, Mining Field Specialist
RE: Blazon Exploration Site B3, CEP/007/009, ACT/007/021,
Folder #7, Carbon County, Utah

Blazon drill site #B3 was inspected by Sandy Pruitt on September 26, 1984, to inspect reclamation of the drill site reported to be complete in a letter dated September 20, 1984. At the time of this inspection the drill pad and access road had been recontoured sufficiently to the original contour. There was some frozen soil evident at the surface of the backfilled areas, differential sediment of backfilled is expected. The area was not scarified or terraced for erosion control. The area was broadcast seeded, no mulch was applied. Large pine trees uprooted during the backfill operation were laid parallel with the slope. No sediment control was provided. Due to late timing the potential for disturbing germinating seeds, crimping mulch into the surface could potentially cause more disturbance than is warranted for the limited protection. A follow-up inspection to determine germination and revegetation success should be conducted next spring.

re

cc: Donna Griffin, OSM
Joe Helfrich, DOGM
Wayne Hedberg, DOGM
Tom Wright, DOGM

Statistics: See Genwal Mine memo dated October 1, 1984
0571Q-21