

0038



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertor
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 30, 1989
8:00 a.m. to noon

gjh
SLL

Permittee and/or Operators Name: North American Equities (NAE) (415)866-7186
Operator's Repr.: William Prince; Holme, Robert & Owen (801)521-5800
Business Address: 50 S. Main Street, Salt Lake City, UT 84114
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): None
State Official(s): Harold G. Sandbeck
Partial: XX Complete: Date of Last Inspection: February 24, 1989
Weather Conditions: Clear and cold
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action:

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(XX)	()	()	(XX)
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION 12/14/88

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The operator was not available for this oversight inspection. Rade Orel accompanied the undersigned inspector on this partial inspection. The mine site and surrounding area was covered with about 2 to 4 feet of snow. We walked up to the entrance gate and were unable to access the mine site due to heavy snow cover.

1. Permits.

Bond The bond expires on June 30, 1989.

Citizens Complaint Rade Orel received a written citizens complaint dated March 20, 1989 from the surface owner. The Division received a copy on March 31, 1989.

Stipulations The Division letter dated March 8, 1989 titled "Review of Stipulation Response and As-Built Report" states that the operator must address the remaining stipulation deficiencies by April 10, 1989.

OSM TDN Issues At this time, there are no TDN issues which need to be addressed.

4. Hydrologic Balance.

c. Sediment Ponds and Impoundments.

The 4th quarter 1988 pond inspection report was checked and no problems were noted.

12. Backfilling and Grading. Rills were evident on the reclaimed highwall slope. As mentioned earlier, the site was inaccessible. Therefore, an inspection of the rills will be accomplished next inspection.

Copy of this Report:

Mailed to: Mr. William Prince (Holme, Robert & Owen), Price Office and

Mailed to: Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number *Harold G. [Signature]* #27 Date: 4/10/89